





report date: 2024-03-29

General information

Make	HYUNDAI
Model	140 CRDI ACTIVE BLUE DRIVE
Colour	White
Year of manufacture	2014
Top speed	125 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



EX64MVW report date: 2024-03-29

MOT history

MOT expiry date	2024-10-06
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	7

MOT #8	2023-09-19 12:40
MOT test number	100868194917
Result	✓ Passed
Next expiry date	2024-10-06

MOT #7	2022-10-06 11:47
MOT test number	294618865043
Result	✓ Passed

MOT #6	2021-10-07 14:54
MOT test number	398891168298
Result	✓ Passed
Minor Offside Rear Registration plate lamp inoperative in the ca	ase of multiple lamps or light sources

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #5 2021-10-06 12:12 689572024803 **MOT** test number Result × Failed Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail

MOT #4		2020-10-03 10:00
MOT test	number	348519376534
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Play in steering rack inner joint(s)	

MOT #3	2019-10-05 13:25
MOT test number	364445534068
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #1

MOT test number

427812991159

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full in		NDAI

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-10-07
Last registration	2023-09-19
Complete history	See info



Registration #1	2014-10-07	28 mi
Registration #2	2017-09-19	35.671 mi
Registration #3	2018-10-05	62.836 mi
Registration #4	2019-10-05	91.975 mi
Registration #5	2020-10-03	100.849 mi
Registration #6		11.777 es
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1610 kg
Max. allowed weight	2080 kg

Additional information

		•
Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number D4FDDU368720