





### General information

Make	FIAT
Model	DOBLO 16V SX MULTIJET
Colour	Blue
Year of manufacture	2016
Top speed	98 mph
0 - 60 mph	5.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	126 g/km
CO2 label	D





## Internet history

Entry 1

Date Pictures 2022-07-29

30

Listing price

View report



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-28
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #7	2023-11-27 15:01
MOT test number	287764299796
Result	✓ Passed
Next expiry date	2024-11-28

МОТ #6	2022-11-29 10:53
MOT test number	728767062742
Result	✓ Passed

MOT #5	2022-01-22 19:31
MOT test number	379396009765
Result	🗸 Passed
Advice Offside Front Steering system slightly rough strut top bearing (2.1.1 (a))	

MOT #4	2021-02-19 14:37
MOT test number	910506673065
Result	🗸 Passed
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weak	cened (1.1.14 (a) (ii))
<b>Advice</b> Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair and rear (1.2.1 (c))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously we	akened (1.1.14 (a) (ii))



МОТ #3	2021-02-19 12:19
MOT test number	754933811557
Result	🗙 Failed
<b>Advice</b> Front Service brake requirements only just met. It would appear that the braking adjustment or repair and rear (1.2.1 (c))	ng system requires
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))
<b>Fail</b> Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b)	) (ii))
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (	1.1.14 (a) (ii))

MOT #2	2020-02-19 12:33
MOT test number	721989152343
Result	✓ Passed
MOT #1	2019-03-27 09:06

MOT #1	2019-03-27 09:06
MOT test number	574414011647
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	



Tax & MOT check

<b>Taxed</b> Tax due: 1 August 2024	✓ MOT Expires: 28 November 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	28 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
******	
************	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



BU16HZG report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-31
Last registration	2023-11-27
Complete history	See info



Registration #1	2016-03-31	25 mi
Registration #2	2019-03-27	22.677 mi
Registration #3	2020-02-19	27.249 mi
Registration #4	2021-02-19	48.494 mi
Registration #5	2021-02-19	48.494 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





## Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1345 kg
Max. allowed weight	2070 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number CarCheck.co.uk	5640817 page 11/11