



report date: 2024-03-29

General information

Make	JAGUAR
Model	XKR
Colour	Grey
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	420 BHP
Max. torque	560 Nm at 4.000 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.8 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.0 mpg
CO2 emission	294 g/km
CO2 label	M





Internet history

Entry 2

Date	2021-11-06
Pictures	50
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-11-05
Pictures	57
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-12
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	13
Total items failed	8

MOT #18	2023-11-14 10:43
MOT test number	727612659177
Result	✓ Passed
Next expiry date	2024-12-12

MOT #17	2022-11-19 08:50
MOT test number	659434387207
Result	✓ Passed
Minor	Front Headlamp lens slightly defective Offside & Nearside (4.1.1 (b) (i))

MOT #16	2022-11-15 12:39
MOT test number	419566128486
Result	✗ Failed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Front Headlamp lens slightly defective Offside & Nearside (4.1.1 (b) (i))
MAJOR	Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt Offside & Nearside (2.1.3 (g) (ii))
MAJOR	Rear Suspension rod ball joint dust cover no longer prevents the ingress of dirt Offside & Nearside (5.3.4 (b) (ii))

MOT #15	2021-12-13 18:26
MOT test number	918840378022
Result	✓ Passed

**MOT #14** 2020-11-12 11:16**MOT test number** 321575922664**Result** ✓ Passed**Advice** Rear exhaust heatshield insecure**Advice** Nearside Front Road wheel slightly distorted inner edge (5.2.2 (c) (i))**MOT #13** 2019-11-04 15:15**MOT test number** 394937498985**Result** ✓ Passed**Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking on inner face (5.2.3 (d) (ii))**Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #12** 2018-10-08 15:31**MOT test number** 392823641321**Result** ✓ Passed**MOT #11** 2017-09-19 15:45**MOT test number** 571958831760**Result** ✓ Passed**MOT #10** 2017-09-19 15:45**MOT test number** 435380857944**Result** ✗ Failed**Pass with rectification** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #9** 2017-01-12 12:59**MOT test number** 748774176360**Result** ✓ Passed

**MOT #8** 2015-10-12 11:55**MOT test number** 844248723134**Result** ✓ Passed**MOT #7** 2015-10-07 09:20**MOT test number** 247852920245**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #6** 2014-07-08 15:29**MOT test number** 529059084183**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Offside front tyre 2x cuts on outer wall**MOT #5** 2013-06-12 12:33**MOT test number** 107043363166**Result** ✓ Passed**MOT #4** 2013-06-11 15:49**MOT test number** 369012563119**Result** ✗ Failed**Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Driver's airbag obviously defective (5.4.1)**Fail** Offside Front Side repeater not working (1.4.A.2c)**Fail** Offside Front Direction indicator not working (1.4.A.2c)



MOT #3	2012-06-01 11:35
MOT test number	719583052107
Result	✓ Passed

MOT #2	2011-06-08 09:51
MOT test number	256299551488
Result	✓ Passed

MOT #1	2010-06-08 17:40
MOT test number	264009650183
Result	✓ Passed

Notice Nearside rear tyre has cut on outer sidewall



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-05-23
Last registration	2023-11-14
Complete history	See info



Registration #1	2007-05-23	15 mi
Registration #2	2010-06-08	19.336 mi
Registration #3	2011-06-08	29.194 mi
Registration #4	2012-06-01	36.026 mi
Registration #5	2013-06-11	43.313 mi
Registration #6	2013-06-12	43.313 mi
Registration #7	2014-07-08	52.803 mi
Registration #8	2015-10-07	58.218 mi
Registration #9	2015-10-12	58.221 mi
Registration #10	2017-01-12	65.112 mi
Registration #11	2017-09-19	65.734 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi
Registration #21	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4794 mm
Wheel base	2752 mm
Kerb weight	1715 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	07020117059G