





General information

| Make | HYUNDAI |
|---------------------|------------------------------|
| Model | TUCSON GDI SE NAV BLUE DRIVE |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 113 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 161 Nm at 4.850 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 147 g/km |
| CO2 label | F |





Internet history


Entry 2

Date Pictures 2021-07-20

5

Listing price

View report



source: cargurus.co.uk

| Entry 1 |
|---------|
|---------|

Date

Pictures

Listing price

2021-07-20 5

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-02 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 1 |

| MOT #4 | 2023-08-03 08:15 |
|---|------------------|
| MOT test number | 869307184615 |
| Result | Passed |
| Next expiry date | 2024-08-02 |
| Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) | |
| Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) | |

| MOT #3 | 2022-06-1 | 13 10:46 |
|----------|--|----------|
| MOT test | number 442574 | 4913270 |
| Result | | Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing Cracking in tread (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing Cracking in tread (5.2.3 (d) (ii)) | |

| MOT #2 | | 2021-05-19 14:41 |
|----------|--|------------------|
| MOT test | number | 523260277028 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |





| MOT #1 | | 2021-05-19 09:12 |
|---|---|------------------|
| MOT test | number | 463350280942 |
| Result | | 🗙 Failed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii) |) |
| Fail Parking brake lever has excessive movement indicating incorrect adjustment 6 clicks before rollers register brake applied (1.1.6 (c)) | | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| | | |



Tax & MOT check

| ✓ | ✓ |
|------------------|-------------------------|
| Taxed | MOT |
| Tax due: | Expires: |
| 1 September 2024 | 2 August 2024 |
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 2 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| - |
|-----|
| AMP |
| |
| |
| - A |
| |
| |
| |
| |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| *********** | |
| ******** | |
| ****** | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-06-15 |
| Last registration | 2023-08-03 |
| Complete history | <u>See info</u> |



| Registration #1 | 2018-06-15 | 26 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-05-19 | 15.011 mi |
| Registration #3 | 2021-05-19 | 15.011 mi |
| Registration #4 | | 11.117 esi |
| Registration #5 | | 11.177 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 85% |
| Pedestrian | 71% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1850 mm |
| Height | 1650 mm |
| Length | 4475 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1464 kg |
| Max. allowed weight | 1895 kg |
| Additional information | |
| Fuel tank capacity | 62 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G4FDJZ630447 |