





report date: 2024-03-29

## General information

Make	CITROEN
Model	C1 PURETECH FEEL
Colour	Grey
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	82 BHP
Max. torque	116 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/11



## Internet history

## Entry 1

Date 2021-01-29

Pictures 7

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-09
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #8	2023-09-08 12:11
MOT test number	966521384109
Result	✓ Passed
Next expiry date	2024-09-09

MOT#7	2023-09-07 16:06
MOT test number	206306760228
Result	<b>×</b> Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	))
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #6	2022-09-05 16:18
MOT test number	152631139186
Result	<b>✓</b> Passed
Advice Rear Tyre slightly damaged/cracking or perishing both sides cr walls and down tread patterns (5.2.3 (d) (ii))	racking /perishing on outer side

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides inner surfaces pitted/corroded and worn (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



MOT #5 2022-09-05 08:31

**MOT test number** 681141839623

Result X Failed

Fail Front Tyre tread depth below requirements of 1.6mm both sides (5.2.3 (e))

**Advice** Offside Rear handbrake low effort

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides inner surfaces pitted/corroded and worn (1.1.14 (a) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing both sides cracking /perishing on outer side walls and down tread patterns (5.2.3 (d) (ii))

Fail Brake lever has insufficient reserve travel (1.1.2 (a))

**Advice** Front Tyre slightly damaged/cracking or perishing both sides crackingperishing on outer side walls and down tread patterns (5.2.3 (d) (ii))

**MOT #4** 2021-09-10 14:38

MOT test number 110701758158

**Result** 
✓ Passed

MOT #3 2020-11-12 10:23

**MOT test number** 998243425631

**Result** ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Very heavily corroded. (1.1.14 (a) (ii))

**MOT #2** 2019-07-30 12:46

**MOT test number** 542806283860

**Result** 
✓ Passed

MOT #1 2018-07-11 10:03

**MOT test number** 524333954318

**Result** 
✓ Passed

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	9 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

•		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-31
Last registration	2023-09-08
Complete history	See info



Registration #1	2015-07-31	26 mi
Registration #2	2018-07-11	14.397 mi
Registration #3	2019-07-30	19.725 mi
Registration #4	2020-11-12	21.463 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		T1.777 es

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	<b>大大大</b> 大大
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



# Dimensions & weight

Width	1884 mm
Height	1460 mm
Length	3466 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1240 kg

## Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	B2020035817

CarCheck.co.uk page 11/11