



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA S
Colour	Silver
Year of manufacture	2005
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-06-03
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2022-10-12
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	29
Total items failed	7

MOT #19	2021-10-13 13:46
MOT test number	545935021220
Result	✓ Passed
Next expiry date	2022-10-12
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2021-10-12 09:55
MOT test number	517972595086
Result	✗ Failed
MAJOR	Front Windscreen washer not working (3.5 (a))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #17**

2020-10-13 12:44

**MOT test number**

113525442827

**Result**

✓ Passed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**(i))  
Nearside Front Coil spring mounting damaged but not seriously weakened Top mount (5.3.1 (b))**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16**

2020-10-12 09:40

**MOT test number**

551377257796

**Result**

✗ Failed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR**

Exhaust emissions likely to be affected by an exhaust leak Emmisions not not tested (8.2.2.1 (b))

**Advice**(i))  
Nearside Front Coil spring mounting damaged but not seriously weakened Top mount (5.3.1 (b))**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR**

Exhaust system insecure (6.1.2 (a))

**MOT #15**

2019-04-25 12:40

**MOT test number**

393089172215

**Result**

✓ Passed

**MOT #14**

2018-04-21 11:40

**MOT test number**

616852064615

**Result**

✓ Passed

**Advice**

Offside Front o/s/f tyre worn on inner edge

**MOT #13** 2017-03-31 14:16**MOT test number** 286495103859**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2017-03-31 09:02**MOT test number** 552598325480**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front brake application uneven (3.7.B.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2016-04-20 09:30**MOT test number** 200798844457**Result** ✓ Passed**MOT #10** 2015-04-10 09:09**MOT test number** 345590205106**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-04-12 10:21**MOT test number** 147632304169**Result** ✓ Passed



MOT #8	2013-04-13 09:35
MOT test number	278273503449
Result	✓ Passed

MOT #7	2012-04-14 11:42
MOT test number	178965002156
Result	✓ Passed
<div><div>Notice</div>Oil leak</div>	

MOT #6	2011-04-09 09:15
MOT test number	816869891073
Result	✓ Passed

MOT #5	2010-03-27 09:27
MOT test number	423996180033
Result	✓ Passed

MOT #4	2009-04-11 12:56
MOT test number	632651309166
Result	✓ Passed
<div><div>Advice</div>Offside Rear Tyre worn close to the legal limit (4.1.E.1)</div>	
<div><div>Advice</div>Front Brake pad(s) wearing thin (3.5.1g)</div>	
<div><div>Advice</div>Offside Front Tyre worn close to the legal limit (4.1.E.1)</div>	
<div><div>Advice</div>Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div>	

**MOT #3** 2009-04-11 11:01**MOT test number** 220481709470**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-04-04 14:44**MOT test number** 543775898048**Result** ✓ Passed**MOT #1** 2008-04-04 09:34**MOT test number** 810665098096**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 May 2022

✕  
MOT

Expired:  
12 October 2022

Tax status	Expired at 31 May 2022
Days left	699 days too late
MOT expiry date	12 October 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-






Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>YH05KLF</b>
Plate since	2019-03-29
Current registration	<b>YH05KLF</b>
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-04-25
Last registration	2021-10-13
Complete history	<a href="#">See info</a>



Registration #1	2005-04-25	28 mi
Registration #2	2008-04-04	37.322 mi
Registration #3	2008-04-04	37.322 mi
Registration #4	2009-04-11	54.659 mi
Registration #5	2009-04-11	54.659 mi
Registration #6	2010-03-27	62.673 mi
Registration #7	2011-04-09	71.651 mi
Registration #8	2012-04-14	80.361 mi
Registration #9	2013-04-13	86.471 mi
Registration #10	2014-04-12	93.133 mi
Registration #11	2015-04-10	100.007 mi
Registration #12	2016-04-09	100.007 mi
Registration #13	2016-04-09	100.007 mi
Registration #14	2016-04-09	100.007 mi
Registration #15	2016-04-09	100.007 mi
Registration #16	2016-04-09	100.007 mi
Registration #17	2016-04-09	100.007 mi
Registration #18	2016-04-09	100.007 mi
Registration #19	2016-04-09	100.007 mi
Registration #20	2016-04-09	100.007 mi
Registration #21	2016-04-09	100.007 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1170 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	303609