






report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	White
Year of manufacture	2015
Top speed	150 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	16.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 75 BHP	
Max. torque	180 Nm at 1.750 rpm	
Engine capacity	1.461 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	54.3 mpg	
Consumption extra urban	67.3 mpg	
Consumption combined	61.4 mpg	
CO2 emission	119 g/km	
CO2 label	С	



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-17
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	8

MOT #10		2024-03-14 09:03
MOT test	number	160121887725
Result		✓ Passed
Next expi	ry date	2025-03-17
Advice	Central Rear Brake pipe corroded, covered in grease or other material Fro	ont to rear (1.1.11 (c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Central Rear Brake pipe corroded, covered in grease or other material Front to Rear (1.1.11 (c))	
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Vice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #9		2023-03-18 09:06
MOT test	number	292664315291
Result		✓ Passed
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		ened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2022-03-16 09:48

MOT test number 770776234874

Result ✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2021-03-18 07:57

MOT test number 582834941851

Result \(\sqrt{Passed} \)

MOT #6 2020-10-01 16:15

MOT test number 482497682684

Result \(\sqrt{Passed} \)

MOT #5 2020-10-01 08:21

MOT test number 143268450711

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip broken (6.1.7 (g) (ii))

MOT #4 2019-10-09 16:36

MOT test number 869096206398

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2019-10-09 11:13

MOT test number 808170672454

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip split (6.1.7 (g) (ii))

MOT #2 2018-11-07 14:37

MOT test number 738768435353

Result \(\sqrt{Passed} \)

MOT #1 2018-11-05 13:58

MOT test number 996215379595

Result × Failed

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	UK UK
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-11-16
Last registration	2024-03-14
Complete history	See info



Registration #1	2015-11-16	15 mi
Registration #2	2018-11-05	16.930 mi
Registration #3	2018-11-07	22.389 mi
Registration #4	2019-10-09	25.306 mi
Registration #5	2019-10-09	25.306 mi
Registration #6	2020-10-01	29.583 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2138 mm
Height	1805 mm
Length	4282 mm
Wheel base	2 mm
Kerb weight	1205 kg
Max. allowed weight	1884 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	2 page 12	2/12

Number of axles2Engine numberD579568