



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Silver
Year of manufacture	2011
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-11-21
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	31
Total items failed	3

MOT #12	2023-11-01 15:47
MOT test number	610039215915
Result	✓ Passed
Next expiry date	2024-11-21
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #11	2022-11-22 16:08
MOT test number	559119116697
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge @1.6mm (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre inner shoulder
Advice	Offside Front Tyre worn close to legal limit/worn on edge @1.6mm (5.2.3 (e))

**MOT #10** 2021-10-25 14:02**MOT test number** 214425413150**Result** ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Nail in tyre

Advice Nearside Rear Tyre worn close to legal limit/worn on edge nail in tread (5.2.3 (e))

Advice Rear seat belts not checked objects on seat

MOT #9 2020-10-13 11:21**MOT test number** 810369940789**Result** ✓ Passed**MOT #8** 2019-10-23 13:45**MOT test number** 398928270701**Result** ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, but not excessively x 2 (1.1.14 (a) (i))

**MOT #7** 2019-10-23 08:25**MOT test number** 801724206385**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))**Fail** Front Windscreen washer not working (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively x 2 (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-10-19 06:47**MOT test number** 335396273182**Result** ✓ Passed**Advice** Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2018-10-16 08:25**MOT test number** 299610524444**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))

**MOT #4** 2017-10-13 11:58**MOT test number** 958588350744**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2016-10-04 07:58**MOT test number** 205750453362**Result** ✓ Passed**MOT #2** 2015-06-26 08:50**MOT test number** 628797075102**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1 2014-06-05 15:12**MOT test number** 548726854108**Result** ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
21 November 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-28
Last registration	2023-11-01
Complete history	See info



Registration #1	2011-06-28	7 mi
Registration #2	2014-06-05	39.122 mi
Registration #3	2015-06-26	48.720 mi
Registration #4	2016-10-04	58.149 mi
Registration #5	2017-10-13	64.262 mi
Registration #6	2018-10-16	70.557 mi
Registration #7	2018-10-19	70.558 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDAH009995