



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI DSG
Colour	Silver
Year of manufacture	2010
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-08-05
Pictures	30
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-12
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	30
Total items failed	13

## MOT #17 2023-10-13 09:33

MOT test number 953825740359

Result ✓ Passed

Next expiry date 2024-10-12

**Minor** Nearside Direction indicator lens defective which has no effect on emitted light Side repeater lens damaged (4.4.1 (b) (i))

**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened Pitted (1.1.14 (a) (ii))

## MOT #16 2023-10-04 14:16

MOT test number 654641305284

Result ✗ Failed

**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened Pitted (1.1.14 (a) (ii))

**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Central Exhaust has a major leak of exhaust gases Exhaust sleeve clamps corroded/broken, exhaust no longer connected to the rear section (6.1.2 (a))

**Fail** Nearside Rear Inner Tyre tread depth below requirements of 1.6mm Tyre slightly distorted on the inner edge. (5.2.3 (e))

**Minor** Nearside Direction indicator lens defective which has no effect on emitted light Side repeater lens damaged (4.4.1 (b) (i))

**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Fail** Emissions unable to be completed Due to exhaust not being connected at the centre to rear section (8.2.2.2 (e))

**MOT #15** 2022-01-19 16:20**MOT test number** 177295356984**Result** ✓ Passed**MOT #14** 2022-01-19 10:47**MOT test number** 972606463832**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 235/45 r17 (5.2.3 (e))**MOT #13** 2021-01-19 10:01**MOT test number** 503413904964**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre stepped inside edge**MOT #12** 2021-01-18 17:03**MOT test number** 385556595023**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre stepped inside edge**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #11** 2019-07-17 14:23**MOT test number** 602401881639**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre stepped on inner edge.
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #10** 2018-07-19 14:29**MOT test number** 476595998279**Result** ✓ Passed**MOT #9** 2018-07-18 09:04**MOT test number** 966335828297**Result** ✗ Failed

- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #8** 2017-06-28 08:54**MOT test number** 370618334838**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2016-06-28 14:19**MOT test number** 217413629847**Result** ✓ Passed**MOT #6** 2016-06-28 11:49**MOT test number** 391014053341**Result** ✗ Failed**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #5** 2016-06-13 10:16**MOT test number** 595711493646**Result** ✓ Passed**MOT #4** 2015-12-04 15:36**MOT test number** 825872610144**Result** ✓ Passed**MOT #3** 2015-03-05 16:31**MOT test number** 707704365032**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2014-03-06 12:55
MOT test number	275435164072
Result	✓ Passed
Notice	Front brakes getting worn
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	No density recorded in smoke test

MOT #1	2013-02-27 08:30
MOT test number	109368053069
Result	✓ Passed
Notice	Nsf tyre 2mm



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
12 October 2024

Tax status		Valid until 1 October
Days left		156
MOT expiry date		12 October 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VU10YKO</b>
Plate since	2019-03-29
Current registration	 <b>VU10YKO</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-04
Last registration	2023-10-13
Complete history	<a href="#">See info</a>



Registration #1	2010-03-04	28 mi
Registration #2	2013-02-27	55.496 mi
Registration #3	2014-03-06	62.194 mi
Registration #4	2015-03-05	68.092 mi
Registration #5	2015-12-04	75.105 mi
Registration #6	2016-06-13	75.139 mi
Registration #7	2016-06-28	75.141 mi
Registration #8	2016-06-28	75.141 mi
Registration #9	2017-06-28	81.020 mi
Registration #10	2018-07-18	95.338 mi
Registration #11	2019-06-28	101.020 mi
Registration #12	2020-06-28	107.020 mi
Registration #13	2021-06-28	113.020 mi
Registration #14	2022-06-28	119.020 mi
Registration #15	2023-06-28	125.020 mi
Registration #16	2024-06-28	131.020 mi
Registration #17	2025-06-28	137.020 mi
Registration #18	2026-06-28	143.020 mi
Registration #19	2027-06-28	149.020 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1574 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CBA 667518