





report date: 2024-03-28

General information

Make	BMW
Model	X6 M50D
Colour	Black
Year of manufacture	2012
Top speed	155 mph
0 - 60 mph	5.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	376 BHP
Max. torque	740 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	40.4 mpg
Consumption combined	36.7 mpg
CO2 emission	204 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-06-19

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-04-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #12	2024-04-05 07:58
MOT test number	404303820811
Result	✓ Passed
Next expiry date	2025-04-04

MOT #11	2022-12-12 11:29
MOT test number	269588888262
Result	✓ Passed

MOT #10	2021-11-11 17:24
MOT test number	927682279662
Result	✓ Passed

MOT #9	2020-11-30 13:27
MOT test number	743498691425
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2019-05-21 12:28 **MOT** test number 536804544775 Result Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing heavily on outer edge (5.2.3 (e)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge Wearing heavily on inner edge (5.2.3 (e)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing heavily on outer edge (5.2.3 (e)) Nearside Rear Tyre worn close to legal limit/worn on edge Wearing heavily on inner edge (5.2.3 **Advice** (e))

MOT #7 2019-05-20 10:09 **MOT** test number 715378362138 Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing heavily on outer edge (5.2.3 (e)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge Wearing heavily on inner edge (5.2.3 (e)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing heavily on outer edge (5.2.3 (e)Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Wearing heavily on inner edge (5.2.3 (e))

MOT #6	2018-09-17 15:06
MOT test number	688004295325
Result	✓ Passed
Advice Minor perishing to all tyres	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2018-09-17 09:42

MOT test number 416275983603

Result X Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Minor perishing to all tyres

MOT #4 2017-09-07 11:31

MOT test number 636128139845

Result ✓ Passed

MOT #3 2016-09-16 14:48

MOT test number 533206510559

Result ✓ Passed

MOT #2 2016-07-14 15:46

MOT test number 784131314637

Result Passed

Advice Offside Rear Tyre worn down on inner edge

Advice Nearside Rear Tyre worn down on inner edge

MOT #1 2015-06-19 16:29

MOT test number 766790175138

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



RR04OCT report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

<u> </u>	
Owner h	าเร†กรพ

o which initiating		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		∋?

	More info >	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	OK NE	
Plate since		
	More info >	>

CarCheck.co.uk page 9/12



RR040C

report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-07-16
Last registration	2024-04-05
Complete history	See info



Registration #1	2012-07-16	26 mi
Registration #2	2015-06-19	22.429 mi
Registration #3	2016-07-14	30.692 mi
Registration #4	2016-09-16	30.723 mi
Registration #5	2017-09-07	38.380 mi
Registration #6	2018-09-17	46.573 mi
Registration #7	2018-09-17	46.575 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		0.77
3		

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



RR040CT

report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1983 mm
Height	1690 mm
Length	4877 mm
Wheel base	2933 mm
Kerb weight	2150 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	90020148

CarCheck.co.uk page 12/12