




General information

Make	FORD
Model	MONDEO
Colour	Grey
Year of manufacture	2015
Gearbox	-

Engine & fuel consumption

Engine capacity	1.560 cc
Fuel type	Diesel
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 4

Date	2023-03-22
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 3




Date	2023-01-11
Pictures	14
Listing price	View report



source: cargurus.co.uk

Entry 2




Date	2021-09-04
Pictures	18
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-06-30
Pictures	43
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-27
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	22
Total items failed	1

MOT #7	2024-04-11 16:52
MOT test number	113869297189
Result	✓ Passed
Next expiry date	2025-04-27
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Undertrays fitted
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #6** 2024-04-11 08:42**MOT test number** 790784157828**Result** ✗ Failed**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Undertrays fitted**MOT #5** 2023-04-28 11:17**MOT test number** 343249297375**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2022-06-07 09:26**MOT test number** 379484591774**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge On 3mm, DOT 3518, 235/50/17 100H XL (5.2.3 (e))**Advice** Brake disc worn, but not excessively All four discs (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge On 3mm, DOT 3518, 235/50/17 100H XL (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #3** 2021-06-30 13:32**MOT test number** 955958272961**Result** ✓ Passed**MOT #2** 2018-08-23 10:47**MOT test number** 738788539444**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2018-05-10 17:06**MOT test number** 822592061661**Result** ✓ Passed**Advice** Under trays fitted



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
27 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	27 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-06-09
Last registration	2024-04-11
Complete history	See info



Registration #1	2015-06-09	23 mi
Registration #2	2018-05-10	14.120 mi
Registration #3	2018-08-23	15.124 mi
Registration #4	2021-06-30	51.770 mi
Registration #5	2022-05-20	55.277 mi
Registration #6	2023-05-20	55.277 mi
Registration #7	2023-05-20	55.277 mi
Registration #8	2023-05-20	55.277 mi
Registration #9	2023-05-20	55.277 mi
Registration #10	2023-05-20	55.277 mi
Registration #11	2023-05-20	55.277 mi
Registration #12	2024-04-11	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	82%
Pedestrian	66%
Safety systems	66%
Overall rating	77%
Video	see crash video



Additional information

Number of seats	5
Engine number	G50710