



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Black
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2022-07-30
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	19
Total items failed	7

MOT #15	2023-08-16 13:03
MOT test number	275741585372
Result	✓ Passed
Next expiry date	2024-08-15

MOT #14	2023-08-16 08:18
MOT test number	230809381765
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #13	2022-07-29 09:54
MOT test number	392885524596
Result	✓ Passed

MOT #12	2021-07-29 08:54
MOT test number	209151091066
Result	✓ Passed

**MOT #11** 2020-07-29 15:36**MOT test number** 943350687331**Result** ✓ Passed**MOT #10** 2020-07-29 12:04**MOT test number** 730669747753**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2019-07-11 11:24**MOT test number** 859369441294**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge & cracks on tread (5.2.3 (e))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #8** 2018-07-21 07:40**MOT test number** 807842216806**Result** ✓ Passed**Advice** Offside Front Nail in tyre**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** All tyres worn on inner edge

**MOT #7** 2018-07-20 11:37**MOT test number** 791463135043**Result** ✗ Failed**Advice** All tyres worn on inner edge**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Nail in tyre**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-07-21 13:46**MOT test number** 421593837860**Result** ✓ Passed**Advice** Nearside Rear tyre worn on inner edges and cracked on tread.**Advice** Offside Rear tyre worn on inner edges and cracked on tread.**MOT #5** 2016-07-27 12:44**MOT test number** 810070416182**Result** ✓ Passed**Advice** Slight cracking in tread rear tyres**MOT #4** 2016-07-27 12:05**MOT test number** 195371128586**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Slight cracking in tread rear tyres



MOT #3	2015-08-06 16:03
MOT test number	840337363865
Result	✓ Passed

MOT #2	2014-12-17 12:48
MOT test number	748791054335
Result	✓ Passed
<div><div>Notice</div>Under-trays fitted obscuring some underside components</div> <div><div>Notice</div>Engine covers fitted obscuring some components in the engine bay</div>	

MOT #1	2014-12-17 11:43
MOT test number	206681254343
Result	✗ Failed
<div><div>Fail</div>Front registration plate delaminated (6.3.1d)</div> <div><div>Notice</div>Under-trays fitted obscuring some underside components</div> <div><div>Notice</div>Engine covers fitted obscuring some components in the engine bay</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	15 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YF61VKE
Plate since	2019-09-28
Current registration	YF61VKE
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-01-06
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	2012-01-06	28 mi
Registration #2	2014-12-17	56.452 mi
Registration #3	2014-12-17	56.452 mi
Registration #4	2015-08-06	63.200 mi
Registration #5	2016-07-27	75.418 mi
Registration #6	2016-07-27	75.418 mi
Registration #7	2017-07-21	84.311 mi
Registration #8	2018-07-20	91.240 mi
Registration #9	2018-07-21	91.242 mi
Registration #10	2019-05-20	91.242 mi
Registration #11	2019-05-20	91.242 mi
Registration #12	2019-05-20	91.242 mi
Registration #13	2019-05-20	91.242 mi
Registration #14	2019-05-20	91.242 mi
Registration #15	2019-05-20	91.242 mi
Registration #16	2019-05-20	91.242 mi
Registration #17	2019-05-20	91.242 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867