



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA S
Colour	Blue
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-30
Pictures	41
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #21 2022-09-21 11:41

MOT test number 194118802859

Result ✓ Passed

Next expiry date 2023-09-29

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Both headlamp aims poor.
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Both headlamps tarnished.
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear box section exhaust corroded & has slight blow.

**MOT #20**

2022-09-08 09:19

MOT test number

642587309695

Result**✗ Failed****Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Both headlamps tarnished.**Fail** Engine mounting damaged or deteriorated resulting in excessive movement Radiator support/ cross member excessively corroded & holes present. (6.1.8 (a) (i))**Advice** Rear box section exhaust corroded & has slight blow.**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Front Windscreen washer not working (3.5 (a))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Both headlamp aims poor.**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (iii))**Fail** Offside Front Windscreen washer not working (3.5 (a))**MOT #19**

2021-09-30 11:31

MOT test number

833018813801

Result**✓ Passed**

**MOT #18**

2021-09-30 07:00

MOT test number

529531852882

Result

✗ Failed

Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Service brake excessively binding (1.2.1 (f))

MOT #17

2020-09-11 12:10

MOT test number

791670592451

Result

✓ Passed

Advice Central Front Lower Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #16

2019-09-17 15:11

MOT test number

641974221396

Result

✓ Passed

MOT #15

2019-09-17 10:07

MOT test number

965704769562

Result

✗ Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14

2018-09-19 10:51

MOT test number

873414084133

Result

✓ Passed



MOT #13	2017-09-11 11:03
MOT test number	314011910963
Result	✓ Passed
MOT #12	2016-09-12 10:10
MOT test number	846981153234
Result	✓ Passed
MOT #11	2015-09-09 15:27
MOT test number	426802022712
Result	✓ Passed
MOT #10	2014-09-10 12:04
MOT test number	968463154237
Result	✓ Passed
MOT #9	2013-09-11 12:37
MOT test number	125574753267
Result	✓ Passed
MOT #8	2012-09-12 12:54
MOT test number	756516452232
Result	✓ Passed
MOT #7	2011-09-07 14:06
MOT test number	396300551462
Result	✓ Passed

**MOT #6** 2010-09-02 14:42**MOT test number** 360305840294**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2009-09-28 16:00**MOT test number** 690391579223**Result** ✓ Passed**MOT #4** 2009-09-28 10:55**MOT test number** 393311179430**Result** ✗ Failed**Fail** Nearside Front brake disc excessively scored (3.5.1h)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front brake application uneven (3.7.B.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #3** 2008-09-22 12:37**MOT test number** 384586268240**Result** ✓ Passed**MOT #2** 2007-09-07 12:00**MOT test number** 140320557281**Result** ✓ Passed



MOT #1	2006-09-26 12:31
MOT test number	512689066258
Result	✓ Passed



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-09-29
Last registration	2022-09-21
Complete history	See info



Registration #1	2003-09-29	10 mi
Registration #2	2006-09-26	23.951 mi
Registration #3	2007-09-07	27.839 mi
Registration #4	2008-09-22	30.599 mi
Registration #5	2009-09-28	33.886 mi
Registration #6	2009-09-28	33.887 mi
Registration #7	2010-09-02	36.245 mi
Registration #8	2011-09-07	37.874 mi
Registration #9	2012-09-12	39.583 mi
Registration #10	2013-09-11	41.138 mi
Registration #11	2014-09-10	42.749 mi
Registration #12	2015-09-09	44.415 mi
Registration #13	2016-09-09	46.080 mi
Registration #14	2017-09-09	47.745 mi
Registration #15	2018-09-09	49.410 mi
Registration #16	2019-09-09	51.075 mi
Registration #17	2020-09-09	52.740 mi
Registration #18	2021-09-09	54.405 mi
Registration #19	2022-09-09	56.070 mi
Registration #20	2023-09-09	57.735 mi
Registration #21	2024-09-09	59.400 mi
Registration #22	2025-09-09	61.065 mi
Registration #23	2026-09-09	62.730 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1170 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	197826