



report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT TDCI T230 LX LWB P/V
Colour	White
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

<b>MOT expiry date</b>	2025-03-13
<b>MOT pass rate</b>	78 %
<b>MOT passed</b>	14
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	28
<b>Total items failed</b>	7

**MOT #18** 2024-03-14 14:12**MOT test number** 469306960476**Result** Passed**Next expiry date** 2025-03-13

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #17** 2023-03-08 15:39**MOT test number** 821695935972**Result** Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16**

2022-03-12 12:07

**MOT test number**

616885481139

**Result**

✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust emits black smoke during acceleration (8.2.1.2 (g))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #15**

2022-03-11 17:29

**MOT test number**

587636582066

**Result**

✗ Failed

**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Direction indicator not working (4.4.1 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust emits black smoke during acceleration (8.2.1.2 (g))**Fail** Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**MOT #14**

2020-06-22 14:46

**MOT test number**

153101377860

**Result**

✓ Passed

**MOT #13** 2019-03-25 11:32**MOT test number** 269652511485**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Power steering close to minimum mark (2.1.5 (b) (i))**Advice** Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2018-02-26 17:37**MOT test number** 600748395273**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Both front tyres heavily worn on the inner edges**MOT #11** 2017-03-14 13:59**MOT test number** 965508350193**Result** ✓ Passed**MOT #10** 2016-02-25 08:01**MOT test number** 493805279010**Result** ✓ Passed



<b>MOT #9</b>	2015-02-12 14:15
---------------	------------------

<b>MOT test number</b>	198923145008
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2014-02-27 09:31
---------------	------------------

<b>MOT test number</b>	155538954072
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2014-02-26 11:35
---------------	------------------

<b>MOT test number</b>	555207454087
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Supplementary Restraint System warning lamp indicates a fault (5.4.2)
-------------	---

<b>MOT #6</b>	2012-12-13 11:10
---------------	------------------

<b>MOT test number</b>	366628342365
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2012-12-13 11:10
---------------	------------------

<b>MOT test number</b>	408038042492
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Windscreen washer provides insufficient washer liquid (8.2.3)
--------------------------------	---

<b>MOT #4</b>	2011-12-13 13:22
---------------	------------------

<b>MOT test number</b>	939197841373
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2010-12-06 10:33
---------------	------------------

<b>MOT test number</b>	282500340312
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #2	2009-12-21 11:36
MOT test number	224675259327
Result	✓ Passed

MOT #1	2009-12-21 11:36
MOT test number	500885559355
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Centre Stop lamp not working (1.2.1b)
Pass with rectification	Offside Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
13 March 2025

<b>Tax status</b>	Valid until 1 May
-------------------	-------------------

<b>Days left</b>	1
------------------	---

<b>MOT expiry date</b>	13 March 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	FV56RXL
Plate since	2024-03-29
Current registration	FV56RXL
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-12-22
Last registration	2024-03-14
Complete history	<a href="#">See info</a>



Registration #1	2006-12-22	15 mi
Registration #2	2009-12-21	26.645 mi
Registration #3	2010-12-06	30.349 mi
Registration #4	2011-12-13	33.249 mi
Registration #5	2012-12-13	37.227 mi
Registration #6	2014-02-26	42.267 mi
Registration #7	2014-02-27	42.277 mi
Registration #8	2015-02-12	45.638 mi
Registration #9	2016-02-25	54.402 mi
Registration #10	2016-03-22	55.277 mi
Registration #11	2016-03-22	55.277 mi
Registration #12	2016-03-22	55.277 mi
Registration #13	2016-03-22	55.277 mi
Registration #14	2016-03-22	55.277 mi
Registration #15	2016-03-22	55.277 mi
Registration #16	2016-03-22	55.277 mi
Registration #17	2016-03-22	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	6U10251