




report date: 2024-03-29

General information

Make	FORD
Model	KUGA TITANIUM
Colour	Black
Year of manufacture	2009
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.3 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.5 mpg
CO2 emission	234 g/km
CO2 label	L





## MOT history

MOT expiry date	2024-05-15
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	24
Total items failed	2

MOT #12	2023-05-16 16:53
MOT test number	814124050384
Result	✓ Passed
Next expiry date	2024-05-15
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #11	2022-05-13 08:33
MOT test number	834921052372
Result	✓ Passed
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #10	2021-05-05 12:25
MOT test number	570363372404
Result	✓ Passed
Advice	Offside Front Nail in tyre
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords and low tread (5.2.3 (d) (i))
Advice	Nearside Front brake caliper missing anti rattle spring
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords and nail (5.2.3 (d) (i))

**MOT #9** 2021-05-04 15:58**MOT test number** 100653172179**Result** ✗ Failed**MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Pass with rectification** Offside Headlamp aim too low and too far to the right. (4.1.2 (a))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front nearside rear and offside front wheel nut 1 per wheel is incorrect**MAJOR** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** Offside Front Nail in tyre**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords and nail (5.2.3 (d) (i))**DANGEROUS** Nearside Rear Tyre has ply or cords exposed 235/45/19 (5.2.3 (d) (ii))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords and low tread (5.2.3 (d) (i))**Advice** Nearside Front brake caliper missing anti rattle spring**MOT #8** 2020-05-04 12:23**MOT test number** 924453813940**Result** ✓ Passed**MOT #7** 2019-05-15 09:09**MOT test number** 320977883979**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #6** 2017-03-16 13:39**MOT test number** 505897029410**Result** ✓ Passed**Advice** Nearside Front tyre and o/s front tyre wearing**MOT #5** 2016-03-11 12:47**MOT test number** 650519413662**Result** ✓ Passed**MOT #4** 2015-04-22 14:19**MOT test number** 285902315120**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-01-08 11:59**MOT test number** 285928705046**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2012-12-03 14:04**MOT test number** 849558732322**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-12-03 14:04**MOT test number** 479638332449**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 May 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	15 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>RV09OVC</b>
Plate since	2024-03-29
Current registration	<b>RV09OVC</b>
Plate since	2024-03-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-03-01
Last registration	2023-05-16
Complete history	<a href="#">See info</a>



Registration #1	2009-03-01	11 mi
Registration #2	2012-12-03	26.980 mi
Registration #3	2015-01-08	40.930 mi
Registration #4	2015-04-22	41.628 mi
Registration #5	2016-03-11	49.768 mi
Registration #6	2017-03-16	58.386 mi
Registration #7	2019-05-20	75.277 mi
Registration #8	2019-05-20	75.277 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1842 mm
Height	1710 mm
Length	4443 mm
Kerb weight	1608 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

9P18241