





report date: 2024-03-28

General information

Make	VAUXHALL
Model	ADAM ENERGISED
Colour	Blue
Year of manufacture	2017
Top speed	102 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.229 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-16

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-24
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #8		2023-11-20 12:34
MOT test	number	956474414954
Result		✓ Passed
Next expi	ry date	2024-11-24
Advice	Parking brake lever travel is slightly high	
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing perished and has a nail in tread (5.2.3 (d) (ii))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d)) (ii))

MOT #7	2022-11-03 15:2
MOT test	
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))	

CarCheck.co.uk page 3/12



MOT #6 2022-11-03 09:55

MOT test number 579453283941

Result X Failed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded on edge (1.1.14 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened corroded on edge (1.1.14 (a) (ii))

Fail Front Windscreen washer not working (3.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Front brake discs are corroded on edge

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #5 2021-11-25 10:56

MOT test number 300044512658

Result \(\sqrt{Passed} \)

MOT #4 2021-05-25 09:36

MOT test number 804611760887

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3 2020-06-04 13:25

MOT test number 460173756247

CarCheck.co.uk page 4/12



MOT #2

MOT test number

Result

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1

MOT test number

2020-05-29 05:22

MOT test number

217123872016

Result

✓ Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Tyne	

Damage 2	
Date	
Category	



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· · · · · · · · · · · · · · · · · · ·	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	

2000000	

Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK NE.
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-06-06
Last registration	2023-11-20
Complete history	See info



Registration #1	2017-06-06	25 mi
Registration #2	2020-06-01	16.039 mi
Registration #3	2020-06-04	16.056 mi
Registration #4	2021-05-25	20.321 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1966 mm
Height	1483 mm
Length	3698 mm
Wheel base	2311 mm
Kerb weight	1011 kg
Max. allowed weight	1470 kg

Additional information

Fuel tank capacity	38 I	
Fuel delivery	Multi-Point Injection	
Number of doors	3	
Number of seats	4	
Number of axles	2	
Engine number	B12XER -19NN8638LWD	

CarCheck.co.uk page 12/12