




report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | VOLVO |
| Model | V70 D5 SE SPORT |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 134 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 182 BHP |
| Max. torque | 400 Nm at 2.000 rpm |
| Engine capacity | 2.400 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 28.8 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 38.2 mpg |
| CO2 emission | 195 g/km |
| CO2 label | J |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-06 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2020-02-21 |
| MOT pass rate | 64 % |
| MOT passed | 9 |
| Failed MOT tests | 5 |
| Total advice items | 18 |
| Total items failed | 10 |

| | |
|------------------|--|
| MOT #14 | 2019-02-22 16:56 |
| MOT test number | 524555269940 |
| Result | ✓ Passed |
| Next expiry date | 2020-02-21 |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Exhaust mounting defective (6.1.2 (a)) |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Offside Front Play in steering rack inner joint(s) |

**MOT #13**

2019-01-11 16:01

MOT test number

190391830073

Result

✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn at outer edge (5.2.3 (e))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Headlamp aim not tested (4.1.2 (b))
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Damaged (6.1.7 (g) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #12

2018-01-12 10:00

MOT test number

921503663872

Result

✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded bulging on pipe indicating corrosion beneath protective layer (3.6.B.2c)

MOT #11

2018-01-11 15:10

MOT test number

547315858763

Result

✗ Failed

- Advice** Offside Rear Brake pipe slightly corroded bulging on pipe indicating corrosion beneath protective layer (3.6.B.2c)
- Fail** Headlamps matched pair are not the same colour (1.7.6)
- Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #10** 2016-08-24 13:04**MOT test number** 377676011886**Result** ✓ Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice O/s w/screen washer weak

MOT #9 2016-08-24 09:17**MOT test number** 673674250734**Result** ✗ Failed

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Advice O/s w/screen washer weak

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #8 2015-07-22 08:50**MOT test number** 325103705255**Result** ✓ Passed**MOT #7** 2014-08-01 15:17**MOT test number** 768773014254**Result** ✓ Passed**MOT #6** 2014-07-29 15:19**MOT test number** 975160814269**Result** ✗ Failed

Fail Offside front brake excessively fluctuating (3.7.B.3)

Fail Nearside front brake excessively fluctuating (3.7.B.3)

**MOT #5** 2013-07-15 11:33**MOT test number** 605176893146**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-04-26 09:06**MOT test number** 247537012177**Result** ✓ Passed**MOT #3** 2011-05-26 10:33**MOT test number** 398066341198**Result** ✓ Passed**MOT #2** 2011-05-26 10:33**MOT test number** 976616941162**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)**MOT #1** 2010-09-16 10:33**MOT test number** 202149050290**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
8 July 2019

X

MOT

Expired:
21 February 2020

| | |
|------------------|---------------------------------|
| Tax status | Expired at 8 July 2019 |
| Days left | 1758 days too late |
| MOT expiry date | 21 February 2020 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2007-09-28 |
| Last registration | 2019-02-22 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-09-28 | 6 mi |
| Registration #2 | 2010-09-16 | 28.788 mi |
| Registration #3 | 2011-05-26 | 32.903 mi |
| Registration #4 | 2012-04-26 | 32.943 mi |
| Registration #5 | 2013-07-15 | 46.115 mi |
| Registration #6 | 2014-07-29 | 55.968 mi |
| Registration #7 | 2014-08-01 | 55.988 mi |
| Registration #8 | 2015-07-22 | 65.058 mi |
| Registration #9 | 2016-05-22 | 75.277 mi |
| Registration #10 | 2017-05-22 | 85.277 mi |
| Registration #11 | 2018-05-22 | 95.277 mi |
| Registration #12 | 2019-05-22 | 105.277 mi |
| Registration #13 | 2020-05-22 | 115.277 mi |
| Registration #14 | 2021-05-22 | 125.277 mi |
| Registration #15 | 2022-05-22 | 135.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1861 mm |
| Height | 1547 mm |
| Length | 4823 mm |
| Wheel base | 2816 mm |
| Kerb weight | 1778 kg |
| Max. allowed weight | 2310 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 564081 |