



PEUGEOT

HX05JVT

report date: 2024-03-28

General information

| | |
|---------------------|--------------------------|
| Make | PEUGEOT |
| Model | BOXER HDI 330 LX SWB C/C |
| Colour | White |
| Year of manufacture | 2005 |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-----------------|----------|
| Engine capacity | 2.178 cc |
| Cylinders | 4 |
| Fuel type | Diesel |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-22 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-17 |
| MOT pass rate | 75 % |
| MOT passed | 18 |
| Failed MOT tests | 6 |
| Total advice items | 21 |
| Total items failed | 13 |

| | |
|------------------|---|
| MOT #24 | 2024-01-03 10:09 |
| MOT test number | 995423262136 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-17 |
| Advice | Offside Front Direction indicator slightly discoloured (4.4.3 (a)) |
| Advice | Nearside Front Direction indicator slightly discoloured (4.4.3 (a)) |

| | |
|-----------------|--|
| MOT #23 | 2022-12-21 09:33 |
| MOT test number | 325861212592 |
| Result | ✓ Passed |
| Advice | Exhaust mounting defective rubbers split (6.1.2 (a)) |

| | |
|-----------------|------------------|
| MOT #22 | 2022-01-18 15:50 |
| MOT test number | 694778223956 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #21 | 2021-06-18 12:37 |
| MOT test number | 579719769886 |
| Result | ✓ Passed |

**MOT #20** 2020-08-10 15:29**MOT test number** 377337147404**Result** ✓ Passed**Advice** Exhaust rusted**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front X member Rusted and holed**MOT #19** 2019-08-09 09:14**MOT test number** 330398003032**Result** ✓ Passed**Advice** Rear exhaust silencer corroded/ deteriorated**Advice** Front crossmember corroded/ holed**MOT #18** 2018-08-08 15:03**MOT test number** 715392863749**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Exhaust box cover rusted**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #17** 2017-08-02 14:34**MOT test number** 802416276372**Result** ✓ Passed**Advice** Nearside Rear tyre sidewall slightly cracked**Advice** Offside Rear tyre sidewall slightly cracked

**MOT #16** 2017-08-02 11:15**MOT test number** 891072303416**Result** ✗ Failed**Advice** Offside Rear tyre sidewall slightly cracked**Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded inner sill / out rigger (2.4.A.3)**Advice** Nearside Rear tyre sidewall slightly cracked**MOT #15** 2016-08-11 07:50**MOT test number** 614211711800**Result** ✓ Passed**MOT #14** 2015-08-12 08:11**MOT test number** 585812999370**Result** ✓ Passed**MOT #13** 2015-08-10 14:32**MOT test number** 801104369398**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #12** 2015-02-03 10:03**MOT test number** 236544135043**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2014-01-06 14:55**MOT test number** 938626904056**Result** ✓ Passed**MOT #10** 2013-01-15 15:34**MOT test number** 765705713069**Result** ✓ Passed**MOT #9** 2013-01-14 15:06**MOT test number** 977254813048**Result** ✗ Failed**Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Nearside Front Rear wheel bearing has excessive play (2.6.2)**Fail** Front front brake application uneven (3.7.B.2)**MOT #8** 2011-10-12 12:51**MOT test number** 395735781466**Result** ✓ Passed**MOT #7** 2011-10-12 09:48**MOT test number** 526995181240**Result** ✗ Failed**Fail** Offside Front Steering rack insecure (2.2.B.1a)**MOT #6** 2010-10-19 17:11**MOT test number** 361862290269**Result** ✓ Passed

**MOT #5** 2010-10-18 09:31**MOT test number** 322871990492**Result** ✗ Failed**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Rear fog lamp not working (1.3.2b)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**MOT #4** 2009-11-10 10:47**MOT test number** 464364419320**Result** ✓ Passed**MOT #3** 2009-03-04 16:02**MOT test number** 252253469079**Result** ✓ Passed**Notice** Surface crack in nearside front disc**MOT #2** 2008-02-27 15:21**MOT test number** 330908658093**Result** ✓ Passed**MOT #1** 2008-02-27 15:21**MOT test number** 820178458067**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
17 January 2025

Tax status

Valid until 1 February

Days left

279

MOT expiry date

17 January 2025

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 25 |
| First mileage registration | 2005-03-21 |
| Last registration | 2024-01-03 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2005-03-21 | 10 mi |
| Registration #2 | 2008-02-27 | 6.332 mi |
| Registration #3 | 2009-03-04 | 10.203 mi |
| Registration #4 | 2009-11-10 | 13.669 mi |
| Registration #5 | 2010-10-18 | 15.950 mi |
| Registration #6 | 2010-10-19 | 15.955 mi |
| Registration #7 | 2011-10-12 | 18.522 mi |
| Registration #8 | 2011-10-12 | 18.522 mi |
| Registration #9 | 2013-01-14 | 21.195 mi |
| Registration #10 | 2013-01-15 | 21.208 mi |
| Registration #11 | 2014-01-06 | 25.734 mi |
| Registration #12 | 2015-02-03 | 31.254 mi |
| Registration #13 | 2015-08-10 | 33.544 mi |
| Registration #14 | 2016-08-20 | 35.377 mi |
| Registration #15 | 2017-08-20 | 35.377 mi |
| Registration #16 | 2018-08-20 | 35.377 mi |
| Registration #17 | 2019-08-20 | 35.377 mi |
| Registration #18 | 2020-08-20 | 35.377 mi |
| Registration #19 | 2021-08-20 | 35.377 mi |
| Registration #20 | 2022-08-20 | 35.377 mi |
| Registration #21 | 2023-08-20 | 35.377 mi |
| Registration #22 | 2024-01-03 | 35.377 mi |
| Registration #23 | 2024-01-03 | 35.377 mi |
| Registration #24 | 2024-01-03 | 35.377 mi |
| Registration #25 | 2024-01-03 | 35.377 mi |



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 2024 mm |
| Kerb weight | 1670 kg |
| Max. allowed weight | 3300 kg |

Additional information

| | |
|-----------------|-------------|
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | DZ354021838 |