



report date: 2024-03-29

General information

Make	MAZDA
Model	6 D BUSINESS LINE
Colour	Blue
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	340 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-04
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-06-15
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	7
Total items failed	10

MOT #13	2023-06-16 14:16
MOT test number	123729639648
Result	✓ Passed
Next expiry date	2024-06-15

MOT #12	2023-06-13 14:05
MOT test number	286874603169
Result	✗ Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Braking system leaking (1.1.3 (d))
Fail	Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #11	2022-06-07 09:45
MOT test number	138333352384
Result	✓ Passed

**MOT #10** 2022-05-31 09:36**MOT test number** 552770691459**Result** ✗ Failed

- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))

**MOT #9** 2021-06-07 14:53**MOT test number** 565762902006**Result** ✓ Passed**MOT #8** 2020-09-28 13:21**MOT test number** 178200953021**Result** ✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #7** 2020-09-28 08:39**MOT test number** 306738776045**Result** ✗ Failed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



<b>MOT #6</b>	2019-09-24 08:21
---------------	------------------

<b>MOT test number</b>	563990098377
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2018-09-24 10:11
---------------	------------------

<b>MOT test number</b>	493278750177
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2017-09-19 08:14
---------------	------------------

<b>MOT test number</b>	375709463516
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2016-09-23 14:33
---------------	------------------

<b>MOT test number</b>	880609687736
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2015-09-24 11:36
---------------	------------------

<b>MOT test number</b>	896989921588
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
---------------	--

<b>MOT #1</b>	2014-09-27 12:06
---------------	------------------

<b>MOT test number</b>	749280874287
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
15 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	15 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-30
Last registration	2023-06-16
Complete history	<a href="#">See info</a>



Registration #1	2011-09-30	6 mi
Registration #2	2014-09-27	23.283 mi
Registration #3	2015-09-24	29.134 mi
Registration #4	2016-09-23	34.165 mi
Registration #5	2017-09-19	36.639 mi
Registration #6	2018-09-24	39.369 mi
Registration #7	2019-09-24	42.592 mi
Registration #8	2020-09-28	44.519 mi
Registration #9	2021-09-28	46.519 mi
Registration #10	2022-09-28	48.519 mi
Registration #11	2023-09-28	50.519 mi
Registration #12	2024-09-28	52.519 mi
Registration #13	2025-09-28	54.519 mi
Registration #14	2026-09-28	56.519 mi
Registration #15	2027-09-28	58.519 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1550 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10291334