



TOYOTA



report date: 2024-03-28

General information

| | |
|---------------------|-----------------------|
| Make | TOYOTA |
| Model | PREVIA VVTI CDX 7 STR |
| Colour | Grey |
| Year of manufacture | 2002 |
| Top speed | 115 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 154 BHP |
| Max. torque | 225 Nm at 4.000 rpm |
| Engine capacity | 2.362 cc |
| Cylinders | 4 |
| Fuel type | Gas / Bi-fuel |
| Consumption city | 19.5 mpg |
| Consumption extra urban | 32.5 mpg |
| Consumption combined | 26.2 mpg |
| CO2 emission | 259 g/km |
| CO2 label | M |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2020-12-30 |
| MOT pass rate | 74 % |
| MOT passed | 17 |
| Failed MOT tests | 6 |
| Total advice items | 36 |
| Total items failed | 20 |

| | |
|------------------|---|
| MOT #23 | 2019-12-31 10:56 |
| MOT test number | 181929079538 |
| Result | ✓ Passed |
| Next expiry date | 2020-12-30 |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) |
| Advice | Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a)) |
| Minor | Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

**MOT #22**

2019-12-31 08:52

MOT test number

778872598276

Result**✗ Failed****Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #21**

2018-12-17 13:58

MOT test number

716241516443

Result**✓ Passed****Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #20**

2017-12-12 14:26

MOT test number

811107984371

Result**✓ Passed****Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #19** 2016-12-13 12:32**MOT test number** 525295345004**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #18** 2015-12-08 14:07**MOT test number** 925743943437**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #17** 2014-12-13 12:41**MOT test number** 106017344398**Result** ✓ Passed**MOT #16** 2014-12-13 11:56**MOT test number** 677567444321**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Stop lamp not working (1.2.1b)

**MOT #15** 2013-11-12 13:25**MOT test number** 788266813315**Result** ✓ Passed**MOT #14** 2013-11-12 09:57**MOT test number** 269536513303**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Rear fog lamp not working (1.3.2b)**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)**Fail** Stop lamp not working (1.2.1b)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #13** 2012-11-14 14:25**MOT test number** 698219912373**Result** ✓ Passed**Advice** Exhaust emits blue smoke during acceleration (7.3.A.2c)**MOT #12** 2011-08-23 10:08**MOT test number** 156785031255**Result** ✓ Passed**MOT #11** 2011-08-23 10:08**MOT test number** 848815131201**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low and too far to the left. (1.8)

**MOT #10**

2011-02-25 15:26

MOT test number

108386251404

Result

✓ Passed

Advice

Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)

Notice

N/s/f tyre slightly pitted

Notice

O/s/r brake disc slightly scored

Advice

Offside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice

O/s/f tyre slightly pitted

Notice

N/s/r brake disc slightly scored

MOT #9

2010-08-19 09:29

MOT test number

484251930299

Result

✗ Failed

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

Advice

Exhaust has a minor leak of exhaust gases (7.1.2)

Pass with rectification

Nearside Rear position lamp(s) not working (1.1.A.3b)

MOT #8

2010-08-19 09:29

MOT test number

174161130282

Result

✓ Passed

Advice

Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #7

2010-07-15 09:27

MOT test number

292246390197

Result

✓ Passed

**MOT #6** 2009-06-19 12:29**MOT test number** 193910379114**Result** ✓ Passed**MOT #5** 2008-12-04 15:14**MOT test number** 494979238317**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2008-03-03 17:11**MOT test number** 912593668085**Result** ✓ Passed**MOT #3** 2007-02-07 17:54**MOT test number** 153898837480**Result** ✓ Passed**MOT #2** 2007-02-06 18:37**MOT test number** 113867637015**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Nearside Stop lamp excessively damaged so that it is not visible from a reasonable distance (1.2.1d)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp aim too high (1.8)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



| | |
|-----------------|------------------|
| MOT #1 | 2006-01-30 09:47 |
| MOT test number | 700080236060 |
| Result | ✓ Passed |



Tax & MOT check

✕
Untaxed

Tax expired:
22 December 2020

✕
MOT

Expired:
30 December 2020

| | |
|------------------|---------------------------------|
| Tax status | Expired at 22 December 2020 |
| Days left | 1225 days too late |
| MOT expiry date | 30 December 2020 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 59 |
| Band | K |
| Single payment (12 months) | £ 385,00,- |
| Single six month payment | £ 211,75,- |
| Total payable by 12 monthly instalments | £ 404,25,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-28 |
| Current registration | ***** |
| Plate since | 2019-06-28 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2002-03-01 |
| Last registration | 2019-12-31 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2002-03-01 | 25 mi |
| Registration #2 | 2006-01-30 | 60.573 mi |
| Registration #3 | 2007-02-06 | 72.134 mi |
| Registration #4 | 2007-02-07 | 72.139 mi |
| Registration #5 | 2008-03-03 | 82.188 mi |
| Registration #6 | 2008-12-04 | 49.006 mi |
| Registration #7 | 2009-06-19 | 65.949 mi |
| Registration #8 | 2010-07-15 | 70.226 mi |
| Registration #9 | 2010-08-19 | 74.138 mi |
| Registration #10 | 2011-02-25 | 87.597 mi |
| Registration #11 | 2011-08-23 | 100.303 mi |
| Registration #12 | 2012-03-20 | 113.277 mi |
| Registration #13 | 2012-09-17 | 126.251 mi |
| Registration #14 | 2013-05-14 | 139.225 mi |
| Registration #15 | 2014-01-11 | 152.199 mi |
| Registration #16 | 2014-07-08 | 165.173 mi |
| Registration #17 | 2015-03-05 | 178.147 mi |
| Registration #18 | 2015-09-02 | 191.121 mi |
| Registration #19 | 2016-04-29 | 204.095 mi |
| Registration #20 | 2017-01-26 | 217.069 mi |
| Registration #21 | 2017-08-23 | 230.043 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|--------|---------|
| Width | 1790 mm |
| Height | 1770 mm |
| Length | 4750 mm |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 76 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number | 2AZ0563631 |