





report date: 2024-03-29

#### General information

Make	VOLVO	
Model	V90 D5 POWERPULSE R-DESIGN PRO AWD	
Colour	Blue	
Year of manufacture	2018	
Top speed	145 mph	
0 - 60 mph	6.9 seconds	
Gearbox	8 speed automatic	

## Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

#### Entry 1

Date2022-02-04Pictures1Listing priceView report



source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MO	T hi	istory	,
----	------	--------	---

MOT expiry date	2025-02-15
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #4		2024-02-12 11:10
MOT test	number	310890806508
Result		✓ Passed
Next expi	ry date	2025-02-15
Advice	Water in fuel light lit	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Engine oil level service required message	

MOT #3	2023-02-09 09:58
MOT test number	265478483265
Result	<b>✓</b> Passed
MOT #2	2022-02-16 09:54
MOT test number	512998134976
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

**MOT #1** 2021-06-28 14:54 563004692678 **MOT** test number ✓ Passed Result **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	15 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CO. C.	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-07-23
Last registration	2024-02-12
Complete history	See info



Registration #1	2018-07-23	22 mi
Registration #2	2021-06-28	30.476 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es

More info >

page 10/11 CarCheck.co.uk



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



## Dimensions & weight

Width	1895 mm
Height	1475 mm
Length	4936 mm
Wheel base	2941 mm
Kerb weight	1783 kg
Max. allowed weight	2400 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number 2459800