





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 LIFE TDI
Colour	White
Year of manufacture	2019
Top speed	107 mph
0 - 100 km/h	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/11




Internet history


Entry 1

Date 2022-03-02

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-07-05
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #6		2023-07-06 09:39
MOT test	number	276973610492
Result		✓ Passed
Next expi	ry date	2024-07-05
Advice	Items removed from driver's view prior to test	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))

MOT #5		2022-03-05 18:20
MOT test	number	607066640043
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exce	essive movement (5.3.4 (a)

CarCheck.co.uk page 3/11



MOT #4 2022-03-03 12:35

MOT test number 193041445753

Result X Failed

Fail Headlamp aim too low (4.1.2 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front CV joint seriously weakened

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #3 2021-02-25 13:12

MOT test number 879121317555

Result ✓ Passed

MOT #2 2021-02-24 11:51

MOT test number 278435385915

Result X Failed

Fail Offside Rear Anti-roll bar pin or bush excessively worn d rubber (5.3.4 (a) (i))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Anti-roll bar pin or bush excessively worn d rubber (5.3.4 (a) (i))

MOT #1 2020-02-27 10:20

MOT test number 757850900698

Result

Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NY
Plate since	
Current registration	NE UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-03-05
Last registration	2023-07-06
Complete history	See info



Registration #1	2019-03-05	26 mi
Registration #2	2020-02-27	64.250 mi
Registration #3	2021-02-24	96.924 mi
Registration #4	2021-02-25	97.096 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

page 10/11 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1793 mm
Height	1831 mm
Length	4878 mm
Wheel base	2 mm
Kerb weight	1640 kg
Max. allowed weight	2350 kg

Additional information

Number of seats	7	
Number of axles	2	
Engine number	DFSD010309	
CarChack co.uk		nage 11/11

CarCheck.co.uk page 11/11