



HONDA




report date: 2024-03-29

General information

Make	HONDA
Model	CR-V I-VTEC SE
Colour	Grey
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	153 BHP
Max. torque	192 Nm at 4.300 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-21
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-26
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #9 2023-08-21 10:57

MOT test number 609156483231

Result ✓ Passed

Next expiry date 2024-08-26

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #8 2022-08-08 14:19

MOT test number 270653873261

Result ✓ Passed

MOT #7 2022-08-08 09:57

MOT test number 796864026543

Result ✗ Failed

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6 2021-08-27 14:22

MOT test number 475009213829

Result ✓ Passed

**MOT #5** 2020-11-25 14:27**MOT test number** 712469604070**Result** ✓ Passed**Advice** Front Shock absorbers has slight external damage to the casing Both Side (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Door's Moulding Missing**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both Side (1.1.14 (a) (ii))**MOT #4** 2019-11-08 14:33**MOT test number** 750993253948**Result** ✓ Passed**Advice** Offside mirror damaged**MOT #3** 2018-11-01 11:09**MOT test number** 323218082717**Result** ✓ Passed**MOT #2** 2017-09-11 12:55**MOT test number** 808475483227**Result** ✓ Passed**MOT #1** 2016-07-14 11:09**MOT test number** 481325086180**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
26 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	26 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 <b>RJ13UVW</b>
Plate since	2019-03-29
Current registration	 <b>RJ13UVW</b>
Plate since	2019-03-29

More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-07-11
Last registration	2023-08-21
Complete history	<a href="#">See info</a>




Registration #1	2013-07-11	7 mi
Registration #2	2016-07-14	25.507 mi
Registration #3	2017-09-11	33.035 mi
Registration #4	2018-11-01	43.428 mi
Registration #5	2019-11-08	52.433 mi
Registration #6	2020-11-25	60.170 mi
Registration #7	2021-05-20	65.277 mi
Registration #8	2021-05-20	65.277 mi
Registration #9	2021-05-20	65.277 mi
Registration #10	2021-05-20	65.277 mi
Registration #11	2023-08-21	65.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1685 mm
Length	4570 mm
Wheel base	2630 mm
Kerb weight	1508 kg
Max. allowed weight	1955 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	R20A91027972