



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO E (64BHP)
Colour	Blue
Year of manufacture	2007
Top speed	101 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	112 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-08
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-26
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	29
Total items failed	23

MOT #21	2024-01-04 18:05
MOT test number	502537378662
Result	✓ Passed
Next expiry date	2025-01-26
Advice	Offside Side repeater slightly discoloured slightly damaged (4.4.3 (a))
Advice	Front and rear bumpers damaged

MOT #20	2024-01-04 10:28
MOT test number	901845058554
Result	✗ Failed
Advice	Front and rear bumpers damaged
Advice	Offside Side repeater slightly discoloured slightly damaged (4.4.3 (a))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt joint dry (6.1.7 (g) (ii))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Nearside Side repeater not working damaged (4.4.1 (a) (ii))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge outer side wall perished (5.2.3 (e))
Fail	Exhaust has a major leak of exhaust gases front pipe flexi (6.1.2 (a))

**MOT #19**

2023-01-17 13:24

**MOT test number**

772147331184

**Result**

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases front and middle. (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear exhaust heat shield insecure.

**MOT #18**

2023-01-03 11:37

**MOT test number**

815602066475

**Result**

✗ Failed

- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Exhaust has a minor leak of exhaust gases front and middle. (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Advice** Rear exhaust heat shield insecure.

**MOT #17**

2022-01-10 14:02

**MOT test number**

364056746144

**Result**

✓ Passed

- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16**

2022-01-07 12:21

**MOT test number**

712544839294

**Result****✗ Failed**

- Fail** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Fail** Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15**

2021-01-25 08:35

**MOT test number**

422200112556

**Result****✓ Passed**

- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14**

2021-01-23 12:51

**MOT test number**

612410819563

**Result****✗ Failed**

- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))



<b>MOT #13</b>	2020-01-25 14:38
<b>MOT test number</b>	203343386176
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

<b>MOT #12</b>	2020-01-25 09:37
<b>MOT test number</b>	328346344351
<b>Result</b>	✗ Failed
<b>Advice</b>	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Exhaust emissions - engine idle speed too high (8.2.1.2 (e))
<b>Fail</b>	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

<b>MOT #11</b>	2019-01-12 15:53
<b>MOT test number</b>	789742030105
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
<b>Advice</b>	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10** 2018-01-27 12:13**MOT test number** 482967610438**Result** ✓ Passed**Advice** Covers fitted obscuring some components**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #9** 2017-01-27 15:57**MOT test number** 795173295769**Result** ✓ Passed**Advice** Covers fitted obscuring some components**MOT #8** 2017-01-27 11:28**MOT test number** 779951508050**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear rear brake binding (3.7.B.1)**Advice** Covers fitted obscuring some components**Fail** Nearside Rear rear brake binding (3.7.B.1)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #7** 2016-01-16 10:53**MOT test number** 683399582247**Result** ✓ Passed**MOT #6** 2015-01-02 10:02**MOT test number** 476122505097**Result** ✓ Passed



<b>MOT #5</b>	2014-01-25 09:14
---------------	------------------

<b>MOT test number</b>	926185424041
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
---------------	---

<b>MOT #4</b>	2013-01-24 14:50
---------------	------------------

<b>MOT test number</b>	496034523082
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2012-01-23 15:01
---------------	------------------

<b>MOT test number</b>	179383122039
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-01-25 14:55
---------------	------------------

<b>MOT test number</b>	197055921425
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2010-01-25 14:57
---------------	------------------

<b>MOT test number</b>	881755920038
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------





Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✓  
**MOT**

**Expires:**  
26 January 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	26 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BL56GNO</b>
Plate since	2024-03-29
Current registration	 <b>BL56GNO</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-01-26
Last registration	2024-01-04
Complete history	<a href="#">See info</a>



Registration #1	2007-01-26	14 mi
Registration #2	2010-01-25	20.044 mi
Registration #3	2011-01-25	26.010 mi
Registration #4	2012-01-23	31.086 mi
Registration #5	2013-01-24	37.118 mi
Registration #6	2014-01-25	41.996 mi
Registration #7	2015-01-02	47.645 mi
Registration #8	2016-01-16	53.498 mi
Registration #9	2017-01-27	58.684 mi
Registration #10	2017-01-27	58.685 mi
Registration #11	2018-01-27	63.863 mi
Registration #12	2019-01-12	67.596 mi
Registration #13	2020-01-27	71.337 mi
Registration #14	2021-01-27	75.077 mi
Registration #15	2022-01-27	78.817 mi
Registration #16	2023-01-27	82.557 mi
Registration #17	2024-01-04	86.297 mi
Registration #18	2024-01-04	90.037 mi
Registration #19	2024-01-04	93.777 mi
Registration #20	2024-01-04	97.517 mi
Registration #21	2024-01-04	101.257 mi
Registration #22	2024-01-04	104.997 mi
Registration #23	2024-01-04	108.737 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1194 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BME244263