



HN53V JF

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY 1.9SDI VAN
Colour	Blue
Year of manufacture	2003
Gearbox	5 speed Manual

Engine & fuel consumption

Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-25
Pictures	22
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-16
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	19
Total items failed	3

MOT #16	2023-05-17 08:30
MOT test number	263578341670
Result	✓ Passed
Next expiry date	2024-05-16
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
Advice	The rear silencer exhaust box is in a corroded condition
Advice	Exhaust has a minor leak of exhaust gases Rear silencer (6.1.2 (a))

MOT #15	2022-04-21 16:19
MOT test number	256492777951
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2022-04-19 14:24

MOT test number

780900803465

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Parking brake lever travel is becoming excessive
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Reverse light not working
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13

2021-05-17 16:02

MOT test number

814839498884

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #12

2017-11-27 08:19

MOT test number

518445458268

Result**✓ Passed**

- Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

**MOT #11** 2016-11-02 14:53**MOT test number** 777988283214**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2015-11-02 13:24**MOT test number** 428727443056**Result** ✓ Passed**MOT #9** 2014-10-17 10:24**MOT test number** 848530994295**Result** ✓ Passed**MOT #8** 2013-11-04 13:57**MOT test number** 549688303376**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2012-11-06 10:06**MOT test number** 497551612343**Result** ✓ Passed**MOT #6** 2011-10-08 09:49**MOT test number** 389261881435**Result** ✓ Passed**MOT #5** 2010-10-30 10:59**MOT test number** 341583400318**Result** ✓ Passed



MOT #4	2009-10-29 11:07
MOT test number	683742909318
Result	✓ Passed
MOT #3	2008-10-28 09:40
MOT test number	421542908380
Result	✓ Passed
MOT #2	2007-10-30 11:44
MOT test number	924463807351
Result	✓ Passed
MOT #1	2006-11-01 14:02
MOT test number	800935906303
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 May 2024

Tax status	Valid until 1 February
-------------------	------------------------

Days left	277
------------------	-----

MOT expiry date	16 May 2024
------------------------	-------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 HN53VJF
Plate since	2019-06-29
Current registration	 HN53VJF
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2003-10-27
Last registration	2023-05-17
Complete history	See info



Registration #1	2003-10-27	12 mi
Registration #2	2006-11-01	24.410 mi
Registration #3	2007-10-30	30.237 mi
Registration #4	2008-10-28	32.950 mi
Registration #5	2009-10-29	34.819 mi
Registration #6	2010-10-30	36.378 mi
Registration #7	2011-10-08	37.868 mi
Registration #8	2012-11-06	39.542 mi
Registration #9	2013-11-04	41.954 mi
Registration #10	2014-11-04	44.366 mi
Registration #11	2015-11-04	46.778 mi
Registration #12	2016-11-04	49.190 mi
Registration #13	2017-11-04	51.602 mi
Registration #14	2018-11-04	54.014 mi
Registration #15	2019-11-04	56.426 mi
Registration #16	2020-11-04	58.838 mi
Registration #17	2021-11-04	61.250 mi
Registration #18	2022-11-04	63.662 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Kerb weight	1105 kg
Max. allowed weight	1730 kg

Additional information

Number of axles	2
Engine number	AYQ 083871