





report date: 2024-03-28

## General information

Make	VOLVO
Model	S60 D3 R-DESIGN
Colour	Grey
Year of manufacture	2013
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	134 BHP	
Max. torque	350 Nm at 1.500 rpm	
Engine capacity	1.984 сс	
Cylinders	5	
Fuel type	Diesel	
Consumption city	47.1 mpg	
Consumption extra urban	68.9 mpg	
Consumption combined	58.9 mpg	
CO2 emission	126 g/km	
CO2 label	D	



CarCheck.co.uk page 1/11



# Internet history

## Entry 1

Date 2021-06-22

Pictures 51

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-06-28
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #10	2023-06-14 12:04
MOT test number	870559614562
Result	<b>✓</b> Passed
Next expiry date	2024-06-28

MOT #9 2023-06-13 11:04

**MOT test number** 122682886498

Result

× Failed

913562475743

**Fail** Offside Front Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt BOOT SPLIT (2.1.3 (g) (ii))

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing OUTER WALL HEAVILY CRACKED/PERISHED (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge TYRE WEARING ON INSIDE AND OUTER TREAD BLOCKS ARE FEATHERED (5.2.3 (e))

Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing OUTER WALL HEAVILY CRACKED/PERISHED (5.2.3 (d) (ii))

Advice

**MOT** test number

Offside Rear Tyre worn close to legal limit/worn on edge TYRE WEARING ON INSIDE (5.2.3 (e))

MOT #8	2022-06-13 16:19
MOT test number	795190698310
Result	<b>✓</b> Passed
MOT #7	2021-06-29 10:56

CarCheck.co.uk page 3/11



MOT test number

Result

Advice Under-trays fitted obscuring some underside components

Advice Offside Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

MOT #5

MOT test number

Result

Advice Under-trays fitted obscuring some underside components

2019-09-12 14:03

808430125278

✓ Passed

MOT test number

Fail Offside Side repeater not working (4.4.1 (a) (ii))

Advice Under-trays fitted obscuring some underside components

 MOT #3
 2018-09-19 11:17

 MOT test number
 439161416906

 Result
 ✓ Passed

 MOT #2
 2017-09-11 11:27

 MOT test number
 972211996745

 Result
 ✓ Passed

MOT #1 2016-09-23 11:23

MOT test number 372991630534

Result ✓ Passed

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	28 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
*******	
***************************************	
*************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK NAME OF THE PROPERTY OF THE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-27
Last registration	2023-06-14
Complete history	See info



Registration #1	2013-09-27	21 mi
Registration #2	2016-09-23	11.589 mi
Registration #3	2017-09-11	14.634 mi
Registration #4	2018-09-19	16.268 mi
Registration #5	2019-09-11	17.323 mi
Registration #6	2019-09-12	17.324 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 10/11



# Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1616 kg
Max. allowed weight	2110 kg

# Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number1404076