





report date: 2024-03-28

## General information

| Make                | HONDA               |
|---------------------|---------------------|
| Model               | CR-V I-VTEC SE PLUS |
| Colour              | Blue                |
| Year of manufacture | 2016                |
| Top speed           | 113 mph             |
| 0 - 60 mph          | 12.3 seconds        |
| Gearbox             | 5 speed automatic   |

## Engine & fuel consumption

| Power                   | 153 BHP             |
|-------------------------|---------------------|
| Max. torque             | 192 Nm at 4.300 rpm |
| Engine capacity         | 1.997 сс            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 28.3 mpg            |
| Consumption extra urban | 47.1 mpg            |
| Consumption combined    | 37.7 mpg            |
| CO2 emission            | 175 g/km            |
| CO2 label               | Н                   |



CarCheck.co.uk page 1/11



## Internet history

#### Entry 2

| Date         | 2021-06-30 |
|--------------|------------|
| <b>5</b> 1 . |            |

Pictures 30

Listing price <u>View report</u>









source: heycar.co.uk

#### Entry 1

| Date          | 2021-05-26         |  |
|---------------|--------------------|--|
| Pictures      | 1                  |  |
| Listing price | <u>View report</u> |  |



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date    | 2025-04-05 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 6          |
| Failed MOT tests   | 0          |
| Total advice items | 11         |
| Total items failed | 0          |

| MOT #6   |  | 2024-04-06 07:53       |
|--|--|------------------------|
| MOT test   | number   | 198629450022           |
| Result   |  | ✓ Passed               |
| Next expi  | ry date  | 2025-04-05             |
| Advice   | Nearside Front Brake disc worn, but not excessively ridged (1.1.14 (a) (i))  |                        |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))       |                        |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing unevenly worn on inner edges (5.2.3 (d) (ii)) |  |                        |
| Advice   | Offside Front Brake disc worn, but not excessively ridged (1.1.14 (a) (i))   |                        |
| Advice   | Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                        |
| Advice (ii))   | Offside Rear Tyre slightly damaged/cracking or perishing unevenly worn on    | inner edges (5.2.3 (d) |

| MOT #5   |   | 2023-04-21 08:10 |
|----------|---|------------------|
| MOT test | number  | 746745694835     |
| Result   |   | ✓ Passed         |
| Advice   | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))           |                  |
| Advice   | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |                  |
| Advice   | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))            |                  |

CarCheck.co.uk page 3/11



MOT test number

Result

Advice Items removed from driver's view prior to test

Advice Under trays fitted

| MOT #3          | 2021-05-18 17:48 |
|-----------------|------------------|
| MOT test number | 740767751774     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #2          | 2020-07-24 13:44 |
| MOT test number | 932957778072     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2010 07 02 12:26 |

| MOT #1          | 2019-07-02 13:26 |
|-----------------|------------------|
| MOT test number | 590330047814     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 4/11



# Tax & MOT check



| Tax status       | Valid until 1 July |
|------------------|--------------------|
| Days left        | 64                 |
| MOT expiry date  | 5 April 2025       |
| Full MOT history | See MOT history    |

## Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | Н          |
| Single payment (12 months)              | £ 290,00,- |
| Single six month payment                | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| e when mistery  |             |
|---|-------------|
| For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full |             |
|   |             |
| manus .   |             |
|   |             |
| ***************************************   |             |
|   |             |
|   |             |
|   |             |
|   |             |
|   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this HONDA had different number plates.  |             |
| Number of plates  | ,           |
|   |             |
| Current registration  | UK UK       |
| Plate since   |             |
| Current registration  | NK NK       |
| Plate since   |             |
|   | More info > |
|   |             |

CarCheck.co.uk page 8/11



#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 9          |
| First mileage registration | 2016-07-28 |
| Last registration          | 2024-04-06 |
| Complete history           | See info   |



| Registration #1 | 2016-07-28 | 6 mi      |
|-----------------|------------|-----------|
| Registration #2 | 2019-07-02 | 13.933 mi |
| Registration #3 | 2020-07-24 | 16.463 mi |
| Registration #4 | 2021-05-18 | 19.234 mi |
| Registration #5 |            | 71.777 66 |
| Registration #6 |            | 71.777 es |
| Registration #7 |            | 11.777 mi |
| Registration #8 |            | 11.177 es |
| Registration #9 |            | 9.77 sc   |

More info >

CarCheck.co.uk page 10/11



# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 93%             |
| Children       | 74%             |
| Pedestrian     | 68%             |
| Safety systems | 66%             |
| Overall rating | 81%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1820 mm |
|---------------------|---------|
| Height              | 1685 mm |
| Length              | 4605 mm |
| Wheel base          | 2630 mm |
| Kerb weight         | 1645 kg |
| Max. allowed weight | 2100 kg |

# Additional information

| Fuel tank capacity | 58 I                  |
|--------------------|-----------------------|
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Number of axles    | 2                     |
| Engine number      | R20A94005061          |

CarCheck.co.uk page 11/11