





report date: 2024-03-29

General information

Make	FIAT
Model	500C ACTIVE
Colour	Grey
Year of manufacture	2012
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-22

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

N/I	α		TC:	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2024-10-02
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	4

MOT #11		2023-10-03 12:11
MOT test	number	771042389074
Result		✓ Passed
Next exp	ry date	2024-10-02
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Nearside Rear Park brake may require attention	
Minor	Offside Windscreen damaged but not adversely affecting driver's view Scratchin	ng (3.2 (a) (i))

MOT #10	2022-09-07 12:33
MOT test number	264102837302
Result	✓ Passed

MOT #9	2022-09-05 11:17

MOT test number 893347306188

Result × Failed

Fail Central Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number
635126982613

Result

Advice
Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor
(i))

Advice
Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT test number

Result

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Exhaust mounting defective clamp corroded trough (6.1.2 (a))

Advice Offside Rear Valve stem slightly damaged (5.2.3 (j))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2019-03-21 11:02 **MOT** test number 215180436149 Result × Failed Fail Offside Front Tyre has ply or cords exposed uneven wear (5.2.3 (d) (ii)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Advice Nearside Front Tyre worn close to legal limit/worn on edge uneven wear (5.2.3 (e)) Advice Offside Rear Valve stem slightly damaged (5.2.3 (j)) **Advice** Rear Exhaust mounting defective clamp corroded trough (6.1.2 (a))

 MOT #3
 2018-04-05 15:19

 MOT test number
 491832136753

 Result
 ✓ Passed

 MOT #2
 2017-03-06 16:19

 MOT test number
 276273899267

 Result
 ✓ Passed

 Advice
 Offside wiper blade split

MOT #1	2016-03-02 14:18
MOT test number	826199692297
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\sim	ner		
- / I I A	Inor	nıc	torv
C) W	V I C I	1115	LUIV

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

HARMAN CO.	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-11-15
Last registration	2023-10-03
Complete history	See info



Registration #1	2012-11-15	28 mi
Registration #2	2016-03-02	29.409 mi
Registration #3	2017-03-06	33.391 mi
Registration #4	2018-04-05	39.464 mi
Registration #5	2019-03-21	47.713 mi
Registration #6	2019-03-21	47.713 mi
Registration #7	2020-10-02	57.403 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 6492127