



report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T3 INSCRIPTION
Colour	Silver
Year of manufacture	2018
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	250 Nm at 1.700 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	132 g/km
CO2 label	E





## Internet history

## Entry 6

Date	2022-03-12
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

## Entry 5

Date	2022-01-05
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk


## Entry 4

Date	2021-12-11
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk

## Entry 3

Date	2021-08-14
Pictures	18
Listing price	<a href="#">View report</a>



source: [heycar.co.uk](https://www.heycar.co.uk)

## Entry 2

Date	2021-08-11
Pictures	19
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

## Entry 1

Date	2021-08-10
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-07-07
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	4
Total items failed	1

MOT #4	2023-07-04 14:43
MOT test number	259317014259
Result	✓ Passed
Next expiry date	2024-07-07

MOT #3	2022-07-08 11:01
MOT test number	492927897078
Result	✓ Passed

MOT #2	2021-06-08 11:17
MOT test number	637378204699
Result	✓ Passed

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Slight damage to outer side wall (5.2.3 (d) (ii))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing Slight damage to both side walls (5.2.3 (d) (ii))

MOT #1	2021-06-08 11:17
MOT test number	225966075235
Result	✗ Failed

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Slight damage to outer side wall (5.2.3 (d) (ii))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing Slight damage to both side walls (5.2.3 (d) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
7 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	7 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>First licence fee (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-06-28
Last registration	2023-07-04
Complete history	<a href="#">See info</a>



Registration #1	2018-06-28	23 mi
Registration #2	2021-06-08	16.552 mi
Registration #3	2021-06-08	16.552 mi
Registration #4	2022-06-08	16.552 mi
Registration #5	2022-06-08	16.552 mi
Registration #6	2022-06-08	16.552 mi
Registration #7	2022-06-08	16.552 mi
Registration #8	2022-06-08	16.552 mi
Registration #9	2022-06-08	16.552 mi
Registration #10	2022-06-08	16.552 mi
Registration #11	2023-07-04	16.552 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1460 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2715067