





report date: 2024-03-29

General information

Make	VOLVO
Pidic	
Model	V50 D3 R-DESIGN
Colour	Grey
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 сс
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	Е



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2022-05-08

Pictures 35

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-05-03
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	6
Total items failed	2

MOT #12	2024-04-12 08:02
MOT test number	302361145195
Result	✓ Passed
Next expiry date	2025-05-03

MOT #11		2024-04-12 08:02
MOT test number		731050280938
Result		× Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #10	2023-04-06 15:51
MOT test number	768578376399
Result	✓ Passed
MOT #9	2022-05-04 11:22
MOT test number	582318338513
Result	✓ Passed

CarCheck.co.uk page 3/12



LX12SMO

report date: 2024-03-29

MOT #8		2021-10-06 08:16
MOT test	number	233338804299
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7	2020-10-12 09:53
MOT test number	743803666197
Result	✓ Passed
Advice Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))	

MOT #6	2019-04-05 09:27
MOT test number	605072124713
Result	✓ Passed
MOT #5	2018-03-26 15:38
MOT test number	885160016388
Result	✓ Passed
Advice Child Seat fitted not allowing full inspection of adult belt	
Advice Rear Direction indicator slightly discoloured both (1.4.A.2f)	

MOT #4		2017-04-13 09:32
MOT test	number	930036896288
Result		✓ Passed
MOT #3		2016-04-09 10:02
MOT test	number	962976960956
Result		✓ Passed
Advice	Child seats fitted unable to carry out full inspection of adult belt	

CarCheck.co.uk page 4/12



LX12SMO

report date: 2024-03-29

 MOT #2
 2015-02-25 15:38

 MOT test number
 615466655059

 Result
 ✓ Passed

 MOT #1
 2015-02-25 15:38

 MOT test number
 469496355023

 Result
 X Failed

 Pass with rectification
 Rear Direction indicator incorrect colour (1.4.A.2f)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	3 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

LX12SMO

report date: 2024-03-29

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

See in this check if this VOLVO had different number plates.

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-09
Last registration	2024-04-12
Complete history	See info



Registration #1	2012-03-09	26 mi
Registration #2	2015-02-25	16.816 mi
Registration #3	2016-04-09	23.210 mi
Registration #4	2017-04-13	27.460 mi
Registration #5	2018-03-26	30.613 mi
Registration #6	2019-04-05	34.075 mi
Registration #7	2020-10-12	39.439 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		0.777 66

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1520 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2
Engine number 1115610