




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-12-26
Pictures	31
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-12-10
Pictures	27
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-22
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	26
Total items failed	0

MOT #15 2023-11-04 13:59

MOT test number 389154597786

Result ✓ Passed

Next expiry date 2024-11-22

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #14 2022-11-07 11:13

MOT test number 791606203543

Result ✓ Passed

- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #13 2021-11-23 10:00

MOT test number 526107619025

Result ✓ Passed



MOT #12	2021-11-13 12:18
MOT test number	757890747695
Result	✗ Failed
MAJOR	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Rear Exhaust system insecure (6.1.2 (a))
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
MAJOR	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Central Exhaust system insecure (6.1.2 (a))
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Advice	Nearside Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11	2020-11-11 13:09
MOT test number	199114532298
Result	✓ Passed



MOT #10	2020-11-10 15:39
MOT test number	337544780908
Result	✗ Failed
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #9	2019-05-01 10:42
MOT test number	902105610048
Result	✓ Passed

MOT #8	2018-05-03 08:40
MOT test number	715175569187
Result	✓ Passed
Advice	Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)
Advice	Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)
Advice	Advise corrosion starting on rear sub frame.

MOT #7	2017-05-09 09:03
MOT test number	187432483226
Result	✓ Passed

MOT #6	2016-05-05 08:10
MOT test number	896734303371
Result	✓ Passed



MOT #5	2015-05-13 08:56
MOT test number	226213835446
Result	✓ Passed
MOT #4	2014-05-08 15:14
MOT test number	659798724193
Result	✓ Passed
MOT #3	2013-05-03 12:40
MOT test number	565153823163
Result	✓ Passed
MOT #2	2012-05-10 10:18
MOT test number	406581532178
Result	✓ Passed
MOT #1	2011-05-06 08:59
MOT test number	698416221186
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
22 November 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-05-13
Last registration	2023-11-04
Complete history	See info



Registration #1	2008-05-13	13 mi
Registration #2	2011-05-06	28.301 mi
Registration #3	2012-05-10	33.044 mi
Registration #4	2013-05-03	35.130 mi
Registration #5	2014-05-08	38.455 mi
Registration #6	2015-05-13	40.852 mi
Registration #7	2016-05-05	43.540 mi
Registration #8	2017-05-09	44.646 mi
Registration #9	2018-05-03	46.544 mi
Registration #10	2019-05-03	48.377 mi
Registration #11	2020-05-03	50.210 mi
Registration #12	2021-05-03	52.043 mi
Registration #13	2022-05-03	53.876 mi
Registration #14	2023-05-03	55.709 mi
Registration #15	2023-05-03	57.542 mi
Registration #16	2023-05-03	59.375 mi
Registration #17	2023-05-03	61.208 mi
Registration #18	2023-05-03	63.041 mi

More info >



Safety ratings

NCAP rating ★★★★☆
Video [see crash video](#)



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564