



AF57SR0

report date: 2024-03-29

General information

Make	KIA
Model	RIO CRDI S
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	235 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg





Internet history

Entry 1	
Date	2021-02-01
Pictures	5
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #18	2023-09-04 13:46
MOT test number	618123974072
Result	✓ Passed
Next expiry date	2024-09-07
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #17	2022-09-08 07:33
MOT test number	494992876642
Result	✓ Passed
Advice	Front Track rod end ball joint has slight play both n/s and o/s (2.1.3 (b) (i))

MOT #16	2021-08-24 14:11
MOT test number	804575898776
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Child Seat fitted not allowing full inspection of adult belt Both rear outer sides ?

MOT #15	2021-08-23 12:34
MOT test number	487985585164
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Child Seat fitted not allowing full inspection of adult belt Both rear outer sides ?
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14**

2020-09-08 12:40

MOT test number

772868960193

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13

2019-08-07 08:37

MOT test number

720909783311

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12

2018-08-13 08:04

MOT test number

578353810190

Result

✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2018-08-13 08:04**MOT test number** 169468948966**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))**MOT #10** 2017-08-14 10:14**MOT test number** 829650981712**Result** ✓ Passed**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Both (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #9** 2016-08-31 08:34**MOT test number** 534919723487**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Both (2.4.G.2)**MOT #8** 2015-09-01 08:23**MOT test number** 509583422831**Result** ✓ Passed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement Both front arm, forward most bushes (2.4.G.2)

**MOT #7** 2015-08-28 08:33**MOT test number** 811709437213**Result** ✗ Failed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement Both front arm, forward most bushes (2.4.G.2)**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2014-08-29 10:31**MOT test number** 819251644284**Result** ✓ Passed**MOT #5** 2013-08-29 08:55**MOT test number** 947501443276**Result** ✓ Passed**MOT #4** 2012-09-03 13:02**MOT test number** 219547742281**Result** ✓ Passed**MOT #3** 2012-09-03 13:02**MOT test number** 545697642266**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #2** 2011-08-31 09:53**MOT test number** 757163641240**Result** ✓ Passed**Notice** Both rear tyre treads starting to split and perish**Notice** Both front tyres worn on inside edges



MOT #1	2010-08-18 11:12
MOT test number	660840430267
Result	✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	AF57SRO
Plate since	2024-03-29
Current registration	AF57SRO
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-03
Last registration	2023-09-04
Complete history	See info



Registration #1	2007-09-03	13 mi
Registration #2	2010-08-18	27.560 mi
Registration #3	2011-08-31	37.178 mi
Registration #4	2012-09-03	45.113 mi
Registration #5	2013-08-29	53.257 mi
Registration #6	2014-08-29	61.506 mi
Registration #7	2015-08-28	68.718 mi
Registration #8	2015-09-01	68.751 mi
Registration #9	2016-08-31	75.224 mi
Registration #10	2017-08-14	80.347 mi
Registration #11	2018-08-31	85.377 mi
Registration #12	2019-08-31	90.377 mi
Registration #13	2020-08-31	95.377 mi
Registration #14	2021-08-31	100.377 mi
Registration #15	2022-08-31	105.377 mi
Registration #16	2023-08-31	110.377 mi
Registration #17	2023-09-04	115.377 mi
Registration #18	2023-09-04	115.377 mi
Registration #19	2023-09-04	115.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1146 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FA6H33039