



RA060DL

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT 7 STR
Colour	Black
Year of manufacture	-
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN

**MOT history****MOT #15** 2022-01-21 13:18**MOT test number** 625248799064**Result** ✓ Passed**Next expiry date** 2023-01-22**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front arm rear bushes (5.3.4 (a) (i))**MOT #14** 2021-01-23 16:10**MOT test number** 805220085680**Result** ✓ Passed**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear round bush (5.3.4 (a) (i))**Advice** Engine covers + under tray fitted**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**MOT #13** 2019-07-20 09:10**MOT test number** 469035794676**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2018-07-14 10:18

MOT test number

563108361649

Result

✓ Passed

- Advice** Brake disc worn, but not excessively Both front (1.1.14 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #11

2018-07-14 10:18

MOT test number

909752544977

Result

✗ Failed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Brake disc worn, but not excessively Both front (1.1.14 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2017-07-18 12:39**MOT test number** 596206317744**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2016-07-18 09:30**MOT test number** 756971998311**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit Outside shoulder (4.1.E.1)**MOT #8** 2015-07-16 07:39**MOT test number** 255437995430**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2014-07-22 07:36**MOT test number** 939373504209**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2013-07-20 07:29**MOT test number** 909801003280**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2012-06-23 07:33**MOT test number** 515405072151**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2011-06-28 14:14**MOT test number** 136259771124**Result** ✓ Passed**Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2010-06-25 11:46**MOT test number** 934406170163**Result** ✓ Passed**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2009-07-11 11:32**MOT test number** 473982399176**Result** ✓ Passed**MOT #1** 2009-07-11 11:32**MOT test number** 921882399151**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RA06ODL
Plate since	2019-06-29
Current registration	 RA06ODL
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-07-21
Last registration	2022-01-21
Complete history	See info



Registration #1	2006-07-21	13 mi
Registration #2	2009-07-11	40.086 mi
Registration #3	2010-06-25	50.631 mi
Registration #4	2011-06-28	64.832 mi
Registration #5	2012-06-23	77.512 mi
Registration #6	2013-07-20	90.227 mi
Registration #7	2014-07-22	101.983 mi
Registration #8	2015-07-16	115.078 mi
Registration #9	2016-07-16	128.173 mi
Registration #10	2017-07-16	141.268 mi
Registration #11	2018-07-16	154.363 mi
Registration #12	2019-07-16	167.458 mi
Registration #13	2020-07-16	180.553 mi
Registration #14	2021-07-16	193.648 mi
Registration #15	2022-01-21	206.743 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	1600 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BKD 486286