





report date: 2024-03-29

General information

Make	NISSAN
Model	370 Z V6 GT EDITION
Colour	White
Year of manufacture	2012
Top speed	155 mph
0 - 60 mph	5.6 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	326 BHP
Max. torque	363 Nm at 5.200 rpm
Engine capacity	3.696 сс
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	36.2 mpg
Consumption combined	26.9 mpg
CO2 emission	245 g/km
CO2 label	L



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 4

Date 2024-02-05

Pictures 0

Listing price View report

source: carcraft.co.uk

Entry 3

Date 2023-07-24

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 2

Date 2023-07-20

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-24

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$			
10.71	α	h	sto	rv
101	() I		510	II V
	•			. ,

MOT expiry date	2025-01-23
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	17
Total items failed	4

MOT #13	2024-01-24 16:10
MOT test number	387353517602
Result	✓ Passed
Next expiry date	2025-01-23

MOT #12	2023-07-26 14:35
MOT test number	893475875417
Result	✓ Passed

MOT #11		2022-08-12 17:06
MOT test	number	798379565599
Result		✓ Passed
Advice	Under tray fitted signs of oil leak	
Advice	Windscreen stone chipped	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm inner (5.2.3 (e))	
Advice	Offside Rear tyre wear 2.5mm inner	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10 2022-08-05 13:56

MOT test number 146661357252

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm inner (5.2.3 (e))

Fail Windscreen washer not working (3.5 (a))

Advice Offside Rear tyre wear 2.5mm inner

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice Under tray fitted signs of oil leak

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Windscreen stone chipped

MOT #9 2021-08-13 09:35

MOT test number 763116677725

Result \(\sqrt{Passed} \)

Minor Window damaged but not adversely affecting driver's view chip (3.2 (a) (i))

MOT #8 2020-09-18 06:41

MOT test number 805125310133

Result

Passed

MOT #7 2019-06-10 14:54

MOT test number 680248546890

Result ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6

MOT test number

Result

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

MOT test number

407347349166

Result

Advice

Offside Rear tyre slight perished on inner side of treads

Advice

Could not verify condition of both front and rear brake pads due to the design of calipers

Advice

Nearside Rear tyre has a small cut on inner wall

MOT test number
766967728833

Result

Advice Could not verify condition of both front and rear brake pads due to the design of calipers

Advice Nearside Rear tyre has a small cut on inner wall

Fail Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

Advice Offside Rear tyre slight perished on inner side of treads

MOT #3	2016-12-09 14:59
MOT test number	786230855073
Result	✓ Passed
MOT #2	2015-07-24 14:12
MOT test number	297725505215
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2015-02-18 11:48

MOT test number 389719545078

CarCheck.co.uk page 6/13



CF12RGF
report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	hictory
UWILEI	HISTOLV

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



CF12RGF
report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-03-01
Last registration	2024-01-24
Complete history	See info



Registration #1	2012-03-01	16 mi
Registration #2	2015-02-18	31.576 mi
Registration #3	2015-07-24	32.648 mi
Registration #4	2016-12-09	39.222 mi
Registration #5	2017-11-03	41.996 mi
Registration #6	2017-11-09	42.164 mi
Registration #7	2018-12-04	46.662 mi
Registration #8	2019-06-10	48.203 mi
Registration #9	2020-09-18	50.388 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 12/13



CF12RGF report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

				_			
ונו	men:	CIOT	nc -	λ.	WAI	α	ht.
וט	пеп	STUI	13	CX.	$VV \subset I$	ш	TTU.

Width	1845 mm
Height	1315 mm
Length	4250 mm
Wheel base	2550 mm
Kerb weight	1508 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	42064A

CarCheck.co.uk page 13/13