



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC TDCI 125
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-31
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-07
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	34
Total items failed	4

MOT #15	2023-06-12 14:36
MOT test number	288222830146
Result	✓ Passed
Next expiry date	2024-07-07
Advice	Offside Rear number plate bulb

MOT #14	2022-07-02 12:51
MOT test number	832809501727
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2022-07-02 12:51
MOT test number	678064302220
Result	✗ Failed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Headlamp aim too low (4.1.2 (a))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2021-07-08 14:58**MOT test number** 282478048438**Result** ✓ Passed**Advice** Chip on screen**Advice** Engine and under covers fitted obscuring some components**MOT #11** 2020-01-10 13:24**MOT test number** 281740720546**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge worn very low (5.2.3 (e))**MOT #10** 2019-01-24 15:56**MOT test number** 815701361655**Result** ✓ Passed**MOT #9** 2018-02-07 15:14**MOT test number** 429067743226**Result** ✓ Passed**MOT #8** 2017-10-27 14:22**MOT test number** 363374334019**Result** ✓ Passed

**MOT #7** 2017-10-11 11:58**MOT test number** 372734023753**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2016-10-21 14:48**MOT test number** 312068642840**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
Bush starting to separate (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Oil leak Filter area**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-10-15 09:56**MOT test number** 743288739920**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit Outside edge wear. (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #4	2014-10-24 11:33
MOT test number	179817894259
Result	✓ Passed
Notice	Oil leak
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Under-trays fitted obscuring some underside components

MOT #3	2013-08-21 11:56
MOT test number	698573333274
Result	✓ Passed

MOT #2	2012-07-09 16:16
MOT test number	937241992134
Result	✓ Passed
Notice	Offside front tyre on 3-4mm
Notice	Nearside front inner wheel rim slightly damaged
Notice	Items removed from driver's view prior to test
Notice	Nearside front tyre split on sidewall & on 2-3mm/wearing on edges



MOT #12012-07-09 15:21

MOT test number837011492142

ResultX Failed

- Notice

Offside front tyre on 3-4mm
- Pass with rectification

Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
- Notice

Nearside front inner wheel rim slightly damaged
- Notice

Items removed from driver's view prior to test
- Fail

Exhaust emits an excessive level of metered smoke (7.4.B.3a)
- Notice

Nearside front tyre split on sidewall & on 2-3mm/wearing on edges



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
7 July 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EA09BYU
Plate since	2024-03-29
Current registration	EA09BYU
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-23
Last registration	2023-06-12
Complete history	See info



Registration #1	2009-06-23	21 mi
Registration #2	2012-07-09	45.359 mi
Registration #3	2012-07-09	45.359 mi
Registration #4	2013-08-21	51.186 mi
Registration #5	2014-10-24	58.021 mi
Registration #6	2015-10-15	63.338 mi
Registration #7	2016-10-21	69.257 mi
Registration #8	2017-10-11	73.265 mi
Registration #9	2017-10-27	73.274 mi
Registration #10	2018-06-20	75.277 mi
Registration #11	2018-06-20	75.277 mi
Registration #12	2018-06-20	75.277 mi
Registration #13	2018-06-20	75.277 mi
Registration #14	2018-06-20	75.277 mi
Registration #15	2018-06-20	75.277 mi
Registration #16	2018-06-20	75.277 mi
Registration #17	2018-06-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	9K80515