





report date: 2024-03-29

General information

| Make | HONDA |
|---------------------|---------------------|
| Model | HR-V I-DTEC SE NAVI |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 119 mph |
| 0 - 60 mph | 10.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP | |
|-------------------------|---------------------|--|
| Max. torque | 300 Nm at 2.000 rpm | |
| Engine capacity | 1.597 cc | |
| Cylinders | 4 | |
| Fuel type | Diesel | |
| Consumption city | 64.2 mpg | |
| Consumption extra urban | 72.4 mpg | |
| Consumption combined | 68.9 mpg | |
| CO2 emission | 108 g/km | |
| CO2 label | В | |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-09-17

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-10-10 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 3 |
| Total items failed | 4 |

| MOT #6 | 2023-09-30 07:34 |
|------------------|------------------|
| MOT test number | 877944243776 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-10 |

| MOT #5 | | 2022-10-10 16:06 |
|----------|---|------------------|
| MOT test | number | 614622039195 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) | |

| MOT #4 | 2021-10-11 11:50 |
|-----------------|------------------|
| MOT test number | 977179247678 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT #3 2021-09-28 09:10 **MOT test number** 441385528606 Result × Failed Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d)) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) **Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

| MOT #2 | 2020-09-24 11:43 |
|-----------------|------------------|
| MOT test number | 397612264044 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2019-03-28 12:10 |
| MOT test number | 465660844214 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 10 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



SX16LBE

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HONDA had different number plates. deer of plates furthe scinors

CarCheck.co.uk page 8/11



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-03-31 |
| Last registration | 2023-09-30 |
| Complete history | See info |



| Registration #1 | 2016-03-31 | 22 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-03-28 | 38.340 mi |
| Registration #3 | 2020-09-24 | 57.620 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 9.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |

More info >

page 10/11 CarCheck.co.uk



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 79% |
| Pedestrian | 72% |
| Safety systems | 71% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| Width | 1772 mm |
|---------------------|---------|
| Height | 1605 mm |
| Length | 4294 mm |
| Wheel base | 2610 mm |
| Kerb weight | 1404 kg |
| Max. allowed weight | 1870 kg |

Additional information

| Fuel tank capacity | 50 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | N16A31116060 |

CarCheck.co.uk page 11/11