





report date: 2024-03-29

General information

Make	MERCEDES
Model	C C200K SE
Colour	Blue
Year of manufacture	2005
Top speed	144 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 сс
Cylinders	4
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	212 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-10-30

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-08
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	19
Total items failed	10

MOT #18	2	2024-01-09 15:13
MOT test	number	928492235284
Result		✓ Passed
Next expi	ry date	2025-01-08
Advice	General under body corrosion	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #17	2022-06-07 13:58
MOT test number	839940769180
Result	✓ Passed

MOT #16		2021-05-19 11:14
MOT test	number	432605843205
Result		✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Oil leak	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #15 2021-05-19 10:15 **MOT** test number 380624346385 Result × Failed **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) Front Windscreen washer not working (3.5 (a)) Fail **Advice** Oil leak Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Fail Front Headlamp aim too high (4.1.2 (a))

MOT #14

MOT test number

944306130378

Result

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Oil leak

MOT #13

MOT test number

Fesult

Advice Central Oil leak, but not excessive (8.4.1 (a) (i))

 MOT #12
 2017-12-22 12:48

 MOT test number
 446156227445

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



Notice

HF05PZP

report date: 2024-03-29

MOT #	11	2017-12-05 12:46
MOT te	est number	280572059732
Result		X Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.2.B.1f)	
Fail	Registration plate lamp not working (1.1.C.1d)	
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Registration plate lamp not working (1.1.C.1d)	
Fail	Service brake: efficiency below requirements (3.7.B.7)	

MOT #10	2016-11-03 11:11
MOT test number	550301576697
Result	✓ Passed
MOT #9	2015-11-16 16:01
MOT test number	713475800902
Result	✓ Passed
MOT #8	2014-10-18 14:23
MOT test number	678461994235
Result	✓ Passed
MOT #7	2013-07-15 15:58
MOT test number	219946293140
Result	✓ Passed
Notice Engine covers fitted obscuring some components in the engine bay	

CarCheck.co.uk page 5/13

Under-trays fitted obscuring some underside components



report date: 2024-03-29

MOT #6	2013-07-15 15:58
MOT test number	647956693104
Result	× Failed
Pass with rectification Nearside Headlamp aim too high (1.8)	
Notice Engine covers fitted obscuring some components in the engine bay	
Notice Under-trays fitted obscuring some underside components	
Pass with rectification Exhaust system not adequately supported (7.1.1)	

MOT #5		2012-02-08 09:59
MOT test	number	917599732004
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #4	2011-01-06 11:24
MOT test number	196196901431
Result	✓ Passed
MOT #3	2010-06-16 09:56
MOT test number	823967160176
Result	✓ Passed
MOT #2	2009-06-04 10:06
MOT test number	864855959111
Result	✓ Passed
MOT #1	2008-06-09 14:05
MOT test number	613751668166
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	8 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date


Category

Type

Damage 2
Date

Category

Туре



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MERCEDES had different number plates. mber of plates -More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-06-24
Last registration	2024-01-09
Complete history	See info



Registration #1	2005-06-24	25 mi
Registration #2	2008-06-09	17.834 mi
Registration #3	2009-06-04	23.727 mi
Registration #4	2010-06-16	28.727 mi
Registration #5	2011-01-06	30.938 mi
Registration #6	2012-02-08	34.677 mi
Registration #7	2013-07-15	42.738 mi
Registration #8	2014-10-18	43.267 mi
Registration #9	2015-11-16	47.482 mi
Registration #10	2016-11-03	53.299 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 au

More info >

CarCheck.co.uk page 12/13



Width	1957 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	1465 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	27194030479106

CarCheck.co.uk page 13/13