



report date: 2024-03-29

General information

Make	NISSAN
Model	QASHQAI TEKNA PLUS 2 DCI
Colour	Black
Year of manufacture	-
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	240 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg





## MOT history

MOT #15	2022-05-21 08:51
MOT test number	618495429916
Result	✓ Passed
Next expiry date	2023-05-23
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14	2021-05-24 10:31
MOT test number	193901795501
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2021-05-24 10:31
MOT test number	253781811372
Result	✗ Failed
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2020-02-18 14:22
MOT test number	951011349397
Result	✓ Passed



**MOT #11** 2020-02-18 10:15**MOT test number** 504842648403**Result** ✗ Failed**MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Position lamp not working n/s and o/s front (4.2.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt n/s and o/s (2.1.3 (g) (ii))**Minor** Brake fluid warning lamp illuminated (1.1.10 (f))**MOT #10** 2019-01-05 12:53**MOT test number** 797212132842**Result** ✓ Passed**MOT #9** 2017-10-24 10:30**MOT test number** 923105014364**Result** ✓ Passed**MOT #8** 2017-02-02 09:20**MOT test number** 193829684138**Result** ✓ Passed**MOT #7** 2016-02-04 12:33**MOT test number** 197563242562**Result** ✓ Passed

**MOT #6** 2016-02-04 10:53**MOT test number** 629267574958**Result** ✗ Failed**Fail** Nearside Front Mechanical brake component has restricted free movement (3.5.1k)**MOT #5** 2015-02-02 12:56**MOT test number** 399643635071**Result** ✓ Passed**Notice** Headlamp masks/converters fitted**Notice** N/s/rear tyre perrished**MOT #4** 2014-02-14 10:54**MOT test number** 738025144071**Result** ✓ Passed**Notice** Nail in offside front tyre**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Headlamp masks/converters fitted**MOT #3** 2013-02-12 15:56**MOT test number** 717323243053**Result** ✓ Passed**MOT #2** 2013-02-12 15:56**MOT test number** 825513943093**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #1	2012-07-23 10:48
MOT test number	416295302226
Result	✓ Passed
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-11
Last registration	2022-05-21
Complete history	<a href="#">See info</a>



Registration #1	2009-09-11	13 mi
Registration #2	2012-07-23	34.189 mi
Registration #3	2013-02-12	36.511 mi
Registration #4	2014-02-14	52.566 mi
Registration #5	2015-02-02	60.886 mi
Registration #6	2016-02-04	79.860 mi
Registration #7	2016-02-04	79.860 mi
Registration #8	2017-02-02	91.059 mi
Registration #9	2018-05-21	91.059 mi
Registration #10	2018-05-21	91.059 mi
Registration #11	2018-05-21	91.059 mi
Registration #12	2018-05-21	91.059 mi
Registration #13	2018-05-21	91.059 mi
Registration #14	2018-05-21	91.059 mi
Registration #15	2018-05-21	91.059 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1780 mm
Height	1645 mm
Length	4525 mm
Wheel base	2765 mm
Kerb weight	1511 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	016663