





### General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Grey
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E







# Internet history

Entry 1

Date Pictures 2022-02-02

18

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-05-09
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	14
Total items failed	5

MOT #11	2023-05-10 13:38
MOT test number	753109059182
Result	🗸 Passed
Next expiry date	2024-05-09
Advice Central Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple la	mps or light sources
(4.7.1 (b) (i))	

MOT #10	2023-05-04 10:19
MOT test number	620475489162
Result	🗙 Failed
<b>Fail</b> Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))	
Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
<b>Minor</b> Nearside Rear Registration plate lamp inoperative in the case of multiple lamps (4.7.1 (b) (i))	or light sources
Fail Front Brakes imbalanced across an axle 34% (1.2.1 (b) (i))	
Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Central Rear Child Seat fitted not allowing full inspection of adult belt	



MOT #9		2022-02-07 13:35
MOT test	number	524167984701
Result		✓ Passed
Advice	Both front wishbone rear bushes slightly perished	
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #8	2021-07-23 11:23
MOT test number	263209700551
Result	✓ Passed

MOT #7	2020-07-23 13:17
MOT test number	385339086317
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lam (4.7.1 (b) (i))	ps or light sources
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2019-07-18 08:51
MOT test number	872564737953
Result	✓ Passed
MOT #5	2018-07-25 07:48
MOT test number	797931447560
Result	✓ Passed
MOT #4	2017-09-12 10:40
MOT test number	248472713567
Result	✓ Passed
Advice Under trays	

WJ62KXR

report date: 2024-03-29





MOT #3	2016-08-11 09:26
MOT test number	303947242927
Result	✓ Passed
Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened	d (3.5.1i)
MOT #2	2016-08-08 10:20
MOT test number	404916833585
Result	× Failed
Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
<b>Fail</b> Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)	
MOT #1	2015-08-27 10:40
MOT test number	768479235221

Result		✓ Passed
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

X Untaxed Tax expired: 1 December 2023	✓ MOT Expires: 9 May 2024
Tax status	Expired at 1 December 2023
Days left	151 days too late
MOT expiry date	9 May 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE
Category	AM
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
**********	
*********	
**********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-20
Last registration	2023-05-10
Complete history	<u>See info</u>



Registration #1	2012-09-20	24 mi
Registration #2	2015-08-27	13.881 mi
Registration #3	2016-08-08	20.762 mi
Registration #4	2016-08-11	20.835 mi
Registration #5	2017-09-12	33.800 mi
Registration #6	2018-07-25	43.286 mi
Registration #7	2019-07-18	51.454 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi

More info  $\rightarrow$ 





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

Number of seats

CarCheck.co.uk

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5

7

### Engine number

CAYCK90899