



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 S
Colour	Red
Year of manufacture	2003
Top speed	130 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-07
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-04-14
<b>MOT pass rate</b>	68 %
<b>MOT passed</b>	19
<b>Failed MOT tests</b>	9
<b>Total advice items</b>	36
<b>Total items failed</b>	17

**MOT #28** 2024-04-04 11:28**MOT test number** 817023131323**Result** ✓ Passed**Next expiry date** 2025-04-14**Advice** Rear Direction indicator slightly discoloured Both sides (4.4.3 (a))**Advice** Front Direction indicator slightly discoloured Both sides (4.4.3 (a))**MOT #27** 2023-04-04 11:02**MOT test number** 354133254828**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))**Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #26**

2023-04-04 11:02

**MOT test number**

166606769122

**Result****✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))**Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #25**

2022-04-06 13:40

**MOT test number**

889924067629

**Result****✓ Passed****Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Tyre worn close to legal limit/worn on edge Inside (5.2.3 (e))**Advice** Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #24** 2022-04-06 10:24**MOT test number** 166134323623**Result** ✗ Failed**Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Tyre worn close to legal limit/worn on edge Inside (5.2.3 (e))**MOT #23** 2021-04-15 08:57**MOT test number** 879333118302**Result** ✓ Passed**MOT #22** 2020-07-21 13:58**MOT test number** 992832849903**Result** ✓ Passed**MOT #21** 2020-07-20 10:56**MOT test number** 346054995887**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #20** 2019-04-16 15:38**MOT test number** 881021257671**Result** ✓ Passed

**MOT #19** 2019-04-16 15:38**MOT test number** 199807819820**Result** ✗ Failed

**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #18** 2018-04-23 08:46**MOT test number** 491630095618**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit on outside edge (4.1.E.1)

**MOT #17** 2017-04-19 14:00**MOT test number** 334216134412**Result** ✓ Passed

**Advice** Nearside Rear tyre becoming worn on outside edge

**MOT #16** 2017-04-18 08:38**MOT test number** 666434579750**Result** ✗ Failed

**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

**Fail** Central Rear Stop lamp not working (1.2.1b)

**Advice** Nearside Rear tyre becoming worn on outside edge

**MOT #15** 2016-04-21 09:26**MOT test number** 255705309578**Result** ✓ Passed

**MOT #14** 2015-04-23 12:27**MOT test number** 205243415169**Result** ✓ Passed**MOT #13** 2014-04-22 09:54**MOT test number** 197852614184**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2013-04-22 09:34**MOT test number** 747862513128**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2013-04-22 09:34**MOT test number** 596052313167**Result** ✗ Failed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10** 2012-04-19 16:14**MOT test number** 265160512484**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2012-04-19 10:20**MOT test number** 847950912111**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #8** 2011-04-21 10:07**MOT test number** 665531211118**Result** ✓ Passed**MOT #7** 2011-04-21 10:07**MOT test number** 838881911111**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2010-04-22 09:31**MOT test number** 672962510161**Result** ✓ Passed



**MOT #5** 2009-04-23 17:00**MOT test number** 551663619118**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2008-05-19 11:19**MOT test number** 764710348198**Result** ✓ Passed**MOT #3** 2008-05-19 11:19**MOT test number** 522870248198**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Power steering pipe(s) or hose(s) leaking (2.3.3b)**MOT #2** 2007-05-21 13:43**MOT test number** 960701347137**Result** ✓ Passed**MOT #1** 2006-05-22 12:37**MOT test number** 243102246181**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 April 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	14 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>DA03WDK</b>
Plate since	2024-03-29
Current registration	<b>DA03WDK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-05-30
Last registration	2024-04-04
Complete history	<a href="#">See info</a>



Registration #1	2003-05-30	26 mi
Registration #2	2006-05-22	23.948 mi
Registration #3	2007-05-21	29.367 mi
Registration #4	2008-05-19	34.978 mi
Registration #5	2009-04-23	40.151 mi
Registration #6	2010-04-22	46.648 mi
Registration #7	2011-04-21	52.812 mi
Registration #8	2012-04-19	59.150 mi
Registration #9	2012-04-19	59.152 mi
Registration #10	2013-04-22	64.908 mi
Registration #11	2014-04-22	69.109 mi
Registration #12	2015-04-23	73.056 mi
Registration #13	2016-04-21	78.412 mi
Registration #14	2017-04-18	82.573 mi
Registration #15	2018-04-18	86.734 mi
Registration #16	2019-04-18	90.895 mi
Registration #17	2020-04-18	95.056 mi
Registration #18	2021-04-18	99.217 mi
Registration #19	2022-04-18	103.378 mi
Registration #20	2023-04-18	107.539 mi
Registration #21	2024-04-04	111.700 mi
Registration #22	2024-04-04	111.700 mi
Registration #23	2024-04-04	111.700 mi
Registration #24	2024-04-04	111.700 mi
Registration #25	2024-04-04	111.700 mi
Registration #26	2024-04-04	111.700 mi

More info >





Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1427 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	91318