



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D4 MOMENTUM AWD
Colour	Grey
Year of manufacture	2017
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	2.8 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-29
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #5	2023-11-13 08:32
MOT test number	876495927430
Result	✓ Passed
Next expiry date	2024-11-29
Advice	Tyre worn close to legal limit/worn on edge All tyres worn on inner edges (5.2.3 (e))

MOT #4	2022-11-16 08:33
MOT test number	298953106573
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3	2021-11-17 07:50
MOT test number	998756252786
Result	✓ Passed

**MOT #2** 2020-11-12 14:28**MOT test number** 835591068728**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge tread very low on inner edge (5.2.3 (e))

MOT #1 2020-11-09 12:23**MOT test number** 146028479373**Result** ✗ Failed

- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Exhaust fumes entering cabin (6.1.2 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge tread very low on inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tread very low on inner edge (5.2.3 (e))



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
29 November 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-11-30
Last registration	2023-11-13
Complete history	See info



Registration #1	2017-11-30	7 mi
Registration #2	2020-11-09	32.634 mi
Registration #3	2020-11-12	32.634 mi
Registration #4	2023-11-13	32.634 mi
Registration #5	2023-11-13	32.634 mi
Registration #6	2023-11-13	32.634 mi
Registration #7	2023-11-13	32.634 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1785 kg
Max. allowed weight	2500 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2244021