



PEUGEOT



GUIFOA

report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER HDI S L1 850
Colour	White
Year of manufacture	2011
Top speed	100 mph
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-04-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	34
Total items failed	6

MOT #15	2024-04-06 13:44
MOT test number	519595967035
Result	✓ Passed
Next expiry date	2025-04-05
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Rear Registration plate lamp insecure (4.7.1 (c) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2024-04-06 13:44
MOT test number	783502275447
Result	✗ Failed
Minor	Offside Rear Registration plate lamp insecure (4.7.1 (c) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2023-03-29 15:00

**MOT test number**

561228172116

**Result**

✓ Passed

**Advice** Front Brake disc worn, but not excessively discs lipped (1.1.14 (a) (i))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12**

2023-03-18 11:31

**MOT test number**

377245004040

**Result**

✗ Failed

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Front Brake disc worn, but not excessively discs lipped (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Hydraulic leak, but not excessive clutch line to clutch slave cylinder leaking due to corroded line (8.4.1 (a) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #11**

2022-03-29 08:22

**MOT test number**

503863936890

**Result**

✓ Passed

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #10**

2021-04-01 15:00

**MOT test number**

891130289069

**Result**

✓ Passed

**MOT #9** 2020-06-10 10:30**MOT test number** 594942323395**Result** ✓ Passed**MOT #8** 2019-05-07 11:40**MOT test number** 205575014975**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-05-07 09:03**MOT test number** 685537545435**Result** ✗ Failed**Advice** Signs of old fuel leak N/S/R**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #6** 2018-05-16 13:10**MOT test number** 207314971817**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #5** 2017-05-31 08:31**MOT test number** 456915665656**Result** ✓ Passed**Advice** Front Oil leak**MOT #4** 2016-05-24 07:47**MOT test number** 124749147900**Result** ✓ Passed**Advice** Front antirollbar fixed in an offset position to nearside**MOT #3** 2015-05-29 09:41**MOT test number** 295279545468**Result** ✓ Passed**Notice** Oil leak**MOT #2** 2015-05-29 09:41**MOT test number** 277259345422**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Notice** Oil leak**MOT #1** 2014-05-02 13:51**MOT test number** 347042124166**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 April 2024

✓  
MOT

Expires:  
5 April 2025

Tax status

Expired at 1 April 2024

Days left

29 days too late

MOT expiry date

5 April 2025

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-31
Last registration	2024-04-06
Complete history	<a href="#">See info</a>



Registration #1	2011-05-31	19 mi
Registration #2	2014-05-02	39.216 mi
Registration #3	2015-05-29	55.200 mi
Registration #4	2016-05-24	64.584 mi
Registration #5	2017-05-31	70.029 mi
Registration #6	2018-05-16	82.012 mi
Registration #7	2019-05-07	93.256 mi
Registration #8	2019-05-07	93.256 mi
Registration #9	2019-05-07	93.256 mi
Registration #10	2019-05-07	93.256 mi
Registration #11	2019-05-07	93.256 mi
Registration #12	2019-05-07	93.256 mi
Registration #13	2019-05-07	93.256 mi
Registration #14	2019-05-07	93.256 mi
Registration #15	2019-05-07	93.256 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1336 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	JBCB0234269