





report date: 2024-03-28

General information

Make	RENAULT
Model	CAPTUR DYNAMIQUE NAV DCI
Colour	Blue
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-11

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-10-04
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #8	2023-10-05 18:05
MOT test number	559403348306
Result	✓ Passed
Next expiry date	2024-10-04

MOT #7	2023-01-20 09:14
MOT test number	318776431068
Result	✓ Passed

MOT #6	2023-01-08 12:08
MOT test number	732858455056
Result	× Failed
Fail Nearside Front Inner Road wheel hadly distorted (5.2.2 (c) (i))	

Fail Nearside Front Inner Road wheel badly distorted (5.2.2 (c) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2022-08-16 15:55 **MOT** test number 680324099308 Result ✓ Passed **Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e)) **Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Tyre slightly damaged/cracking or perishing tyres perished all around (5.2.3 (d) (ii)) **Advice** Service light on dash **Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge 3.0mm (5.2.3 (e))

MOT #4

MOT test number

653932998585

Result

Advice Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

MOT test number

Result

Advice Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

Pass with rectification Offside Rear fog lamp not working (4.5.1 (a) (ii))

MOT #2

MOT test number

Result

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2019-07-22 17:53

MOT test number 538981997263

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full		ULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-01
Last registration	2023-10-05
Complete history	See info



Registration #1	2016-09-01	6 mi
Registration #2	2019-07-22	43.105 mi
Registration #3	2020-08-10	51.003 mi
Registration #4		11.777 es
Registration #5	2021-07-09	57.182 mi
Registration #6		0.074
		11.777 ea 11.777 ea
Registration #6		11.777 ea 11.777 ea
Registration #6 Registration #7		11,777-00 11,777-00 11,777-00

More info >

CarCheck.co.uk page 11/12



HX66VMP report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1178 kg
Max. allowed weight	1727 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number D109887