



TOYOTA

N15R00

report date: 2024-03-28

General information

Make	TOYOTA
Model	ALPHARD
Colour	White
Year of manufacture	2004
Gearbox	-

Engine & fuel consumption

Engine capacity	2.360 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 2



Date	2022-08-21
Pictures	43
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-08
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	26
Total items failed	8

MOT #11	2024-01-23 13:43
---------	------------------

MOT test number	835242865205
-----------------	--------------

Result	✓ Passed
Next expiry date	2025-01-30
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear tyre worn on inner edge and slightly misshaped
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords inner side wall (5.2.3 (d) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #10**

2024-01-12 13:01

MOT test number

626974640220

Result

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Fail** Rear fog lamp switch missing (4.5.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords inner side wall (5.2.3 (d) (i))
- Advice** Offside Rear tyre worn on inner edge and slightly misshaped
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Fail** Rear fog lamp missing (4.5.1 (a) (ii))

MOT #9

2023-01-14 12:31

MOT test number

302119701608

Result

✓ Passed

MOT #8

2023-01-14 12:31

MOT test number

135595896519

Result

✗ Failed

- Pass with rectification** Rear fog lamp switch inoperative (4.5.3 (a))
- Pass with rectification** Offside Rear Rear fog lamp likely to become detached (4.5.1 (c) (ii))
- Pass with rectification** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #7** 2022-01-31 13:42**MOT test number** 841931492003**Result** ✓ Passed**MOT #6** 2020-12-19 15:42**MOT test number** 644159719541**Result** ✓ Passed**MOT #5** 2019-12-20 15:22**MOT test number** 388835154809**Result** ✓ Passed**MOT #4** 2018-12-27 12:36**MOT test number** 794739566479**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Suspension arm attachment bracket/mounting damaged but its strength is not seriously reduced both sides (5.3.3 (b) (i))**MOT #3** 2018-12-24 16:47**MOT test number** 621978152546**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Suspension arm attachment bracket/mounting damaged but its strength is not seriously reduced both sides (5.3.3 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #2	2017-11-07 15:36
MOT test number	221740192484
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

MOT #1	2017-11-06 11:34
MOT test number	923224377449
Result	✗ Failed
Fail	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
Advice	Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 November
-------------------	------------------------

Days left	186
------------------	-----

MOT expiry date	30 January 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-05-22
Last registration	2024-01-23
Complete history	See info



Registration #1	2015-05-22	11 mi
Registration #2	2017-11-06	85.952 mi
Registration #3	2017-11-07	79.830 mi
Registration #4	2018-12-24	94.172 mi
Registration #5	2018-12-27	94.174 mi
Registration #6	2019-12-20	101.169 mi
Registration #7	2020-12-19	103.714 mi
Registration #8	2021-05-20	103.714 mi
Registration #9	2021-05-20	103.714 mi
Registration #10	2021-05-20	103.714 mi
Registration #11	2021-05-20	103.714 mi
Registration #12	2021-05-20	103.714 mi
Registration #13	2021-05-20	103.714 mi
Registration #14	2021-05-20	103.714 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Number of seats 8

Engine number 2AZ