



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF GT TDI 140
Colour	Grey
Year of manufacture	-
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	9
Listing price	View report



source: autoonline.co.uk

**MOT history**

MOT #18	2022-02-28 16:49
MOT test number	155459721708
Result	✓ Passed
Next expiry date	2023-02-27
Advice	Coolant leak
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front lower rear (5.3.4 (a) (i))

MOT #17	2022-02-28 16:45
MOT test number	803135479620
Result	✗ Failed
Advice	Coolant leak no antifreeze in expansion bottle
Fail	Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front lower rear (5.3.4 (a) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2022-02-24 09:19

MOT test number

362148972765

Result**✗ Failed****Advice** Coolant leak no antifreeze in expansion bottle**Fail** Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Road wheel badly distorted split (5.2.2 (c) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Rear Anti-roll bar linkage pin or bush likely to become detached broken (5.3.4 (a) (ii))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front lower rear (5.3.4 (a) (i))**Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #15**

2021-02-19 12:52

MOT test number

192889276712

Result

✓ Passed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn edges (5.2.3 (e))**Advice** Headlight beam patterns a little blurred**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn inside (5.2.3 (e))**Advice** Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity Both tail lights (4.2.3 (b) (ii))**MOT #14**

2021-02-19 08:25

MOT test number

545774371634

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn edges (5.2.3 (e))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect No beam image (4.1.2 (c))**Advice** All position lamps have a product on the lenses but not adversely affecting light output Sort of a tinted mesh pattern fitted to all lights (4.2.3 (b) (ii))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn inside (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction Illuminated - Codes P3101, P3102 & P0691 stored (8.2.2.2 (g))**Fail** Offside Headlamp aim projected beam image is obviously incorrect No beam image (4.1.2 (c))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #13

2019-04-26 15:52

MOT test number

570278019649

Result		✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Engine oil on minimum level	
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Both sides front & rear lamps covered in tinted mesh	
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))	
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Coolant on minimum level	
Minor	Suspension arm ball joint dust cover severely deteriorated both sides front (5.3.4 (b) (i))	
Advice	Offside sill damaged	
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #12**

2019-04-24 16:25

MOT test number

849079552456

Result**✗ Failed**

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Both sides front & rear lamps covered in tinted mesh

Minor Suspension arm ball joint dust cover severely deteriorated both sides front (5.3.4 (b) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Coolant on minimum level

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside sill damaged

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Engine oil on minimum level

MOT #11

2017-10-21 13:46

MOT test number

366369645637

Result**✓ Passed****MOT #10**

2017-10-20 09:58

MOT test number

128095097250

Result**✗ Failed**

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #9** 2016-10-14 09:42**MOT test number** 319652676199**Result** ✓ Passed**MOT #8** 2015-10-13 10:36**MOT test number** 464728173079**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit tracked to inner edge (4.1.E.1)**Advice** Synthetic covering to all light surfaces**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Advise batt temp retainer**MOT #7** 2015-10-13 10:36**MOT test number** 297731118083**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit tracked to inner edge (4.1.E.1)**Advice** Synthetic covering to all light surfaces**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Advise batt temp retainer**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-10-17 12:49**MOT test number** 138300494279**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #5 2014-10-17 10:44**MOT test number** 759800994207**Result** ✗ Failed

- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-10-21 11:56**MOT test number** 327194493437**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3**

2012-09-18 16:57

MOT test number

665682162246

Result

✓ Passed

- Notice** O/s/r tyre worn unevenly on inner edge
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2

2012-09-18 15:19

MOT test number

586032562263

Result

✗ Failed

- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Advice** Offside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** N/s/f fog lamp lense cracked
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** O/s/r tyre worn unevenly on inner edge
- Notice** Under-trays fitted obscuring some underside components

MOT #1

2011-09-15 15:06

MOT test number

386828051463

Result

✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LD58CWZ
Plate since	2019-06-29
Current registration	 LD58CWZ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-10-06
Last registration	2022-02-28
Complete history	See info



Registration #1	2008-10-06	25 mi
Registration #2	2011-09-15	59.352 mi
Registration #3	2012-09-18	89.101 mi
Registration #4	2012-09-18	89.101 mi
Registration #5	2013-10-21	110.922 mi
Registration #6	2014-10-17	125.269 mi
Registration #7	2014-10-17	125.269 mi
Registration #8	2015-10-13	138.602 mi
Registration #9	2015-10-13	138.602 mi
Registration #10	2016-10-14	144.399 mi
Registration #11	2016-10-14	144.399 mi
Registration #12	2016-10-14	144.399 mi
Registration #13	2016-10-14	144.399 mi
Registration #14	2016-10-14	144.399 mi
Registration #15	2016-10-14	144.399 mi
Registration #16	2016-10-14	144.399 mi
Registration #17	2016-10-14	144.399 mi
Registration #18	2016-10-14	144.399 mi
Registration #19	2016-10-14	144.399 mi
Registration #20	2016-10-14	144.399 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKD C72022