




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CARAVELLE T30 SWB W/V 130TDI
Colour	Beige
Year of manufacture	2004
Top speed	103 mph
0 - 60 mph	16.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.0 mpg
CO2 emission	216 g/km
CO2 label	K





**Internet history**

**Entry 1**

Date	2021-07-07
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-11
MOT pass rate	65 %
MOT passed	17
Failed MOT tests	9
Total advice items	50
Total items failed	20

MOT #26 2024-04-12 13:03

MOT test number 519354858411

Result ✔ Passed

Next expiry date 2025-04-11

**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Advice** Exhaust outer skins corroded

MOT #25 2024-04-12 13:03

MOT test number 879075009801

Result ✘ Failed

**Pass with rectification** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Advice** Exhaust outer skins corroded



**MOT #24** 2022-09-29 10:57

**MOT test number** 721800269104

**Result** ✓ Passed

- Advice** Centre/rear exhaust corroded
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Upper shocker mountings noisy
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #23** 2021-09-08 11:18

**MOT test number** 706245318413

**Result** ✓ Passed

- Advice** Centre & rear exhaust corroded
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #22** 2020-09-23 15:37

**MOT test number** 866236071186

**Result** ✓ Passed

- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #21** 2020-09-18 13:44

**MOT test number** 337156936230

**Result** ✗ Failed

- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Headlamp levelling device inoperative (4.1.5 (a))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))



MOT #20 2019-09-04 14:09

MOT test number 471778372608

Result ✔ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Exhaust centre and tail box corroded

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19 2018-09-03 15:00

MOT test number 375560403597

Result ✔ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #18 2018-08-30 10:48

MOT test number 264652983096

Result ✘ Failed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**Fail** Front Tyre tread depth below requirements of 1.6mm s (5.2.3 (e))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Fail** Engine mounting excessively loose (6.1.8 (a) (ii))



MOT #17 2017-09-04 15:40

MOT test number 297354419293

Result ✔ Passed

- Advice** Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #16 2017-09-04 08:32

MOT test number 290312837061

Result ✘ Failed

- Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Fail** Rear fog lamp not working (1.3.2b)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



**MOT #15** 2016-09-02 06:42

**MOT test number** 113875230170

**Result** ✔ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Passenger seat(s) missing at time of test
- Advice** Center box corroded

**MOT #14** 2016-08-22 08:56

**MOT test number** 856896502667

**Result** ✘ Failed

- Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Center box corroded
- Advice** Passenger seat(s) missing at time of test
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13** 2015-08-20 09:43

**MOT test number** 886003355826

**Result** ✔ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear cuts to tread



MOT #12 2015-08-19 08:56

MOT test number 883469018249

Result ✗ Failed

**Fail** Rear Rear fog lamp not working (1.3.2b)

**Advice** Offside Rear cuts to tread

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2014-09-03 12:45

MOT test number 738536444217

Result ✓ Passed

MOT #10 2014-09-03 12:45

MOT test number 355366444220

Result ✗ Failed

**Pass with rectification** Offside Front Registration plate lamp not working (1.1.C.1d)

**Pass with rectification** Offside Rear Rear fog lamp not working (1.3.2b)

MOT #9 2013-09-13 10:40

MOT test number 209196353206

Result ✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #8 2012-09-05 16:50

MOT test number 448759242232

Result ✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



**MOT #7** 2012-09-05 13:08

**MOT test number** 529079542245

**Result** ✗ Failed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2011-09-14 12:05

**MOT test number** 306857851447

**Result** ✓ Passed

**MOT #5** 2010-09-09 10:37

**MOT test number** 624882650250

**Result** ✓ Passed

**MOT #4** 2009-09-09 11:41

**MOT test number** 850982359267

**Result** ✓ Passed

- Notice** Rear no plate water ingressed
- Notice** Stonechip in windscreen

**MOT #3** 2008-09-10 13:03

**MOT test number** 312594758428

**Result** ✓ Passed



**MOT #2** 2007-09-19 10:16

**MOT test number** 194352167257

**Result** ✔ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #1** 2007-09-19 10:16

**MOT test number** 901862767282

**Result** ✘ Failed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
11 April 2025

**Tax status** Valid until 1 July

**Days left** 63

**MOT expiry date** 11 April 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	OY54JWE
Plate since	2019-03-29
Current registration	OY54JWE
Plate since	2019-03-29

More info >



**Finance check**

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	26
<b>First mileage registration</b>	2004-09-08
<b>Last registration</b>	2024-04-12
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2004-09-08	21 mi
<b>Registration #2</b>	2007-09-19	50.585 mi
<b>Registration #3</b>	2008-09-10	55.057 mi
<b>Registration #4</b>	2009-09-09	63.307 mi
<b>Registration #5</b>	2010-09-09	69.250 mi
<b>Registration #6</b>	2011-09-14	74.409 mi
<b>Registration #7</b>	2012-09-05	78.914 mi
<b>Registration #8</b>	2012-09-05	78.914 mi
<b>Registration #9</b>	2013-09-13	84.059 mi
<b>Registration #10</b>	2014-09-03	88.473 mi
<b>Registration #11</b>	2015-08-19	93.024 mi
<b>Registration #12</b>	2015-08-20	93.024 mi
<b>Registration #13</b>	2016-08-22	101.840 mi
<b>Registration #14</b>	2016-08-22	101.840 mi
<b>Registration #15</b>	2016-08-22	101.840 mi
<b>Registration #16</b>	2016-08-22	101.840 mi
<b>Registration #17</b>	2016-08-22	101.840 mi
<b>Registration #18</b>	2016-08-22	101.840 mi
<b>Registration #19</b>	2016-08-22	101.840 mi
<b>Registration #20</b>	2016-08-22	101.840 mi
<b>Registration #21</b>	2016-08-22	101.840 mi
<b>Registration #22</b>	2016-08-22	101.840 mi
<b>Registration #23</b>	2016-08-22	101.840 mi
<b>Registration #24</b>	2016-08-22	101.840 mi
<b>Registration #25</b>	2016-08-22	101.840 mi
<b>Registration #26</b>	2016-08-22	101.840 mi

**More info** >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2242 mm
Height	1969 mm
Length	4890 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	AXD 036309