



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 TDI P/V
Colour	Grey
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.9 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 3

Date 2022-07-22

Pictures 12

Listing price [View report](#)




source: cargurus.co.uk

Entry 2

Date 2021-10-09

Pictures 18

Listing price [View report](#)





source: autotrader.co.uk

Entry 1

Date 2021-08-26

Pictures 8

Listing price [View report](#)



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-14
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	24
Total items failed	8

MOT #14	2023-07-12 08:26
MOT test number	560803864075
Result	✓ Passed
Next expiry date	2024-07-14
Minor	Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear silencer outer skin corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13	2023-07-12 08:26
MOT test number	155560742120
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear silencer outer skin corroded
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))

MOT #12	2022-07-15 13:50
MOT test number	253544419285
Result	✓ Passed

**MOT #11**

2021-10-29 09:53

**MOT test number**

390573682135

**Result**

✓ Passed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor**

Nearside Windscreen wiper blade defective (3.4 (b) (i))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**MOT #10**

2021-01-21 11:42

**MOT test number**

283906085595

**Result**

✓ Passed

**Advice**

Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Exhaust deteriorated

**MOT #9**

2020-02-03 08:36

**MOT test number**

938065455652

**Result**

✓ Passed

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #8** 2019-02-01 10:57**MOT test number** 920968115492**Result** ✓ Passed**Advice** Front arms rear bushes worn**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-01-31 15:41**MOT test number** 640505156873**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front arms rear bushes worn**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #6** 2017-10-10 14:53**MOT test number** 104193316280**Result** ✓ Passed**MOT #5** 2017-10-06 11:29**MOT test number** 274372840827**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed inner edge (4.1.D.1b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Advice** Nearside Front Tyre worn close to the legal limit both edges (4.1.E.1)

**MOT #4** 2015-11-30 12:17**MOT test number** 598852238723**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2014-12-09 14:02**MOT test number** 437693344485**Result** ✓ Passed**MOT #2** 2014-12-08 08:50**MOT test number** 558452744367**Result** ✗ Failed**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #1** 2013-12-12 14:10**MOT test number** 985266843331**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
14 July 2024

<b>Tax status</b>	Valid until 1 August
-------------------	----------------------

<b>Days left</b>	94
------------------	----

<b>MOT expiry date</b>	14 July 2024
------------------------	--------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-01-05
Last registration	2023-07-12
Complete history	<a href="#">See info</a>



Registration #1	2011-01-05	28 mi
Registration #2	2013-12-12	50.761 mi
Registration #3	2014-12-08	63.322 mi
Registration #4	2014-12-09	63.337 mi
Registration #5	2015-11-30	75.276 mi
Registration #6	2017-10-06	93.265 mi
Registration #7	2017-10-10	93.400 mi
Registration #8	2019-01-31	107.986 mi
Registration #9	2019-02-01	107.999 mi
Registration #10	2019-05-20	121.277 mi
Registration #11	2019-05-20	121.277 mi
Registration #12	2019-05-20	121.277 mi
Registration #13	2019-05-20	121.277 mi
Registration #14	2019-05-20	121.277 mi
Registration #15	2019-05-20	121.277 mi
Registration #16	2019-05-20	121.277 mi
Registration #17	2019-05-20	121.277 mi
Registration #18	2019-05-20	121.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2283 mm
Height	2476 mm
Length	5292 mm
Kerb weight	1912 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	CAA 197076