



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D4 SE NAV
Colour	Silver
Year of manufacture	2016
Top speed	137 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-05-29
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-01
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #7	2023-05-15 12:37
MOT test number	786966682613
Result	✓ Passed
Next expiry date	2024-06-01

MOT #6	2022-05-12 13:42
MOT test number	979824912085
Result	✓ Passed
Advice	Both front tyres wearing inner edges
Advice	Rear Brake pad(s) wearing thin Worn to 1.5mm (1.1.13 (a) (ii))

MOT #5	2021-05-14 08:37
MOT test number	878153727501
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Bald inner edge (5.2.3 (e))

**MOT #4** 2021-05-13 10:25**MOT test number** 564815927661**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Bald inner edge (5.2.3 (e))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2020-06-02 13:30**MOT test number** 347694254314**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Tyre slightly damaged/cracking or perishing both rear cracking and treads wearing out of shape (5.2.3 (d) (ii))**MOT #2** 2019-05-16 12:35**MOT test number** 354590630104**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2019-05-16 12:35**MOT test number** 302015411722**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
1 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-05-20
Last registration	2023-05-15
Complete history	See info



Registration #1	2016-05-20	17 mi
Registration #2	2019-05-16	34.498 mi
Registration #3	2019-05-16	34.498 mi
Registration #4	2020-06-02	45.445 mi
Registration #5	2021-05-13	53.360 mi
Registration #6	2022-05-20	55.277 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2022-05-20	55.277 mi
Registration #9	2023-05-15	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2106 mm
Height	1547 mm
Length	4814 mm
Wheel base	2816 mm
Kerb weight	1752 kg
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1583015