



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | CITROEN |
| Model | C4 PURETECH FLAIR |
| Colour | Red |
| Year of manufacture | 2015 |
| Top speed | 106 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 80 BHP |
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 107 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-29 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-07 |
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 15 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #9 | 2023-06-06 12:14 |
| MOT test number | 528115076445 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-07 |
| Advice | Exhaust has a minor leak of exhaust gases (6.1.2 (a)) |

| | |
|-----------------|---|
| MOT #8 | 2023-06-06 10:33 |
| MOT test number | 528936612354 |
| Result | ✗ Failed |
| DANGEROUS | Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| Advice | Exhaust has a minor leak of exhaust gases (6.1.2 (a)) |
| MAJOR | Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) |

| | |
|-----------------|---|
| MOT #7 | 2022-06-08 13:58 |
| MOT test number | 673230911136 |
| Result | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Minor | Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) |

**MOT #6** 2021-03-01 11:12**MOT test number** 504395168342**Result** ✓ Passed**MOT #5** 2020-08-26 10:00**MOT test number** 335667963783**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #4** 2019-08-27 13:21**MOT test number** 188773232166**Result** ✓ Passed**MOT #3** 2019-08-15 07:18**MOT test number** 483842140998**Result** ✗ Failed**MAJOR** Horn sound not in accordance with requirements (7.7 (c))**DANGEROUS** Tyre tread depth below requirements of 1.6mm Both Front (5.2.3 (e))**MAJOR** Exhaust system insecure (6.1.2 (a))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))**DANGEROUS** Tyre tread depth below requirements of 1.6mm Both Rear (5.2.3 (e))**MAJOR** Brake disc significantly and obviously worn Both Rear (1.1.14 (a) (i))**MAJOR** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))**MOT #2** 2019-01-21 16:38**MOT test number** 317341713790**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #1 | 2018-01-29 11:26 |
| MOT test number | 227065548711 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
7 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 7 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2015-01-31 |
| Last registration | 2023-06-06 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-01-31 | 27 mi |
| Registration #2 | 2018-01-29 | 42.570 mi |
| Registration #3 | 2019-01-21 | 59.204 mi |
| Registration #4 | 2019-08-15 | 67.182 mi |
| Registration #5 | 2019-08-27 | 67.187 mi |
| Registration #6 | 2020-08-26 | 72.546 mi |
| Registration #7 | 2020-08-26 | 72.546 mi |
| Registration #8 | 2020-08-26 | 72.546 mi |
| Registration #9 | 2020-08-26 | 72.546 mi |
| Registration #10 | 2020-08-26 | 72.546 mi |
| Registration #11 | 2020-08-26 | 72.546 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 83% |
| Children | 74% |
| Pedestrian | 33% |
| Safety systems | 40% |
| Overall rating | 67% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1729 mm |
| Height | 1480 mm |
| Length | 4157 mm |
| Wheel base | 2595 mm |
| Kerb weight | 965 kg |
| Max. allowed weight | 1500 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B2150067940 |