





General information Make RENAULT Model CAPTUR EXPRESSIONPLUS CONVENIENCE **ENERGYTCE S/S** Colour Orange Year of manufacture 2014 **Top speed** 106 mph 0 - 60 mph 12.6 seconds Gearbox 5 speed Manual

Engine & fuel consumption

Power	90 BHP	
Max. torque	135 Nm at 2.500 rpm	
Engine capacity	898 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	47.0 mpg	
Consumption extra urban	64.0 mpg	
Consumption combined	56.5 mpg	
CO2 emission	114 g/km	
CO2 label	С	







Internet history

Entry 1

Date

Pictures

2021-01-22

6

Listing price

WE ARE OPEN ONLINE

CLICK AND COLLECT

TLESS H

View report



source: yesauto.com



MOT history

MOT expiry date	2024-09-17
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	21
Total items failed	2

MOT #11	2023-09-18 18:05
MOT test number	944729673799
Result	✓ Passed
Next expiry date	2024-09-17

MOT #10		2023-09-15 14:22
MOT test	number	768990893720
Result		🗙 Failed
MAJOR	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Advice	Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))	

МОТ #9	2022-12-22 14:12
MOT test number	736229772737
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front run flat tyre fitted	
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	





MOT #8		2022-12-22 11:00
MOT test number		142528382739
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front r	run flat tyre fitted	
Minor Offside Front Wir	ndscreen wiper blade defective (3.4 (b) (i))	
Advice Front Brake disc	worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front	Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR Nearside Front I dirt (5.3.4 (b) (ii))	ower Anti-roll bar linkage ball joint dust cover no longe.	er prevents the ingress of
Advice Front Outer Bra	ke pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7	2021-12-29 12:31
MOT test number	182115033897
Result	✓ Passed

MOT #6	2021-12-18 10:40	
MOT test numbe	er 473202280660	
Result	× Failed	
DANGEROUS (d) (ii))	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3	
MAJOR Offsic	de Front Tyre(s) with different structures are fitted across the same axle (5.2.3 (c))	
DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))		
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Rear	fog lamp does not emit a steady red light (4.5.4 (a))	





MOT #5	2020-11-05 10:10
MOT test number	881409459253
Result	Passed
MOT #4	2019-11-15 11:56
MOT test number	835327331740
Result	✓ Passed
MOT #3	2018-11-19 16:44
MOT test number	535996256347
Result	Passed
MOT #2	2018-01-29 09:00
MOT test number	897126735941
Result	✓ Passed
MOT #1	2017-01-28 11:23
MOT test number	653750692135
Result	Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 17 September 2024
Tax status	Valid until 1 September
Days left	124
MOT expiry date	17 September 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Reduction a	
Plane anna	
Current registration	
Current registration Plate since	





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-01-31
Last registration	2023-09-18
Complete history	See info



Registration #1	2014-01-31	25 mi
Registration #2	2017-01-28	24.955 mi
Registration #3	2018-01-29	34.268 mi
Registration #4	2018-11-19	39.488 mi
Registration #5	2019-11-15	43.032 mi
Registration #6	2020-11-05	45.166 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 esi





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1089 kg
Max. allowed weight	1663 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12